C	ERTIFIED LAND CORNER RESTORATION	
State of Wisconsin		•
State of Wisconsin  County of Forest	SS.	
Township 35 North	day of June corner of Section corner of Section 24  Range 14 East Fourth Principal Meridian, ence I established a new monument and accessories as described heris corner:	as described
Description of original monumen	t and accessories and subsequent restorations:	•
80 chains North between 23 Elm 14, N47E, 76 lks. Sugar 15, N62E, 79 lks.	3 & 24, set post	
Sugar 10, S16W, 41 1ks.		•
escription of corner evidence for	ound:	
	cal resident Mr. Clark testifies that he has seen	
scribing in tree. Iron pin bears S47W, 76 11		
Dug up old pin in road and	d found old post when reaching natural soil.	
filled with concrete with Monument set 1.0 foot belonged Southeast corner of house Southeast corner of metal	North of road bears N61W, 173.30 feet	76, S-802
	JEAN F. RESVICE RHINELANDER WIS.  Resident witnesses	I T T T
	Dated at Rhinelander Wisconsin, this 13 day of	Mav
Sec. 24	Signature Jean F. Resvick Title Land Surveyor, or other duly authorized Surveyors Registration No. S-802 DOCUMENT NUMBER	eyord official)
	Office of Register of Deeds County of Forest	
- Corner monument restored	! hereby certify that the within instrument was filed in this office on the 27th day of June 19.77, and was	ce for record filed in Book
rownship35.North, Rang	No. Page No. of County Records.  Signature Title Register of Section 24 , Index No. N-21 , Page No.	Deeds Vo.