## U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Corner to Section <u>18-19</u> T35 N, R 14 E <u>quarter</u> (Section/Quarter) RI4E 35N

O = Corner monument restored.



Set a 2"x 36" aluminum monument with cap stamped for corner. Ties are to aluminum nails driven into the tree centers which trees were blazed and scribed. Bearings are magnetic.

5-1 N39°E 28.14

5-2 S67°E 25.34 5-3 S21°W 22.95

5-4 N51°W 15.27

History of original corner establishment, record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence, and what you found and how the monument was set.

In 1859 James McBride, contract surveyor, set this corner at 40 chains west of the northeast corner of section 19 and marked the following bearing trees: Birch 35 links

14" N69W Sugar S34W

21 "

At single proportionate search area I found a number of old sugar stumps but none of them witnessing any post evidence. However, a CCC tag was found tacked onto a small diameter Maple tree near this corner location. I scraped the ground in a 20 ft radius from this CCC tag and located a squared 3" post hole with vertical wood fibers. S34W for 13.98 ft. a hardwood stump hole was noted with Maple clump growing just north of the hole. The other BT, N69W for 23 feet fell in an old logging road now used as snowmobile route. I accepted the post evidence found near the CCC tag and monumented same. Cutting east and west from this corner fell along an old blazed line during true line placement.

In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material, except wood other than bearing trees.) Also, show any material discrepancies between the corner restored or re-established and the location of any other previous corner location or occupation.

> sign post west 0.50 9" Maple

2"x30" aluminum monument

Kim H Pritzlaff, RLS No. 1259

(Type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature

1993

Date

Certificate Ready For Filing:

District Ranger

## MAINTENANCE RECORD

Condition of Monument	<u> </u>		
Condition of Ties			
New Ties, if any:			
		•	
Date	Signature		
Condition of Monument			
Condition of Ties		•	
New Ties, if any:			
		• •	
Date	Signature		
<u> </u>		<u> </u>	
Condition of Monument			
Condition of Ties			
Condition of Ties			
Condition of Ties  New Ties, if any:			
•			
•			
New Ties, if any:			
New Ties, if any:			

