CERTIFIED LAND	CORNER RESTORATION
State of Wisconsin ss. County of Forest	
County of <u>Forest</u>	-
I found evidence of the North Quarte Township 35 North Range	fy that on the 11th day of August 19.83., cr Section 22 15 East Fourth Principal Meridian, as described new monument and accessories as described hereon to per-
Description of original monument and accessories an	d subsequent restorations:
Surveyed in 1859 by James McBride 39.75 chains, set wood post Basswood, 14", S.36°E., 14 links, 9.24 fee Sugar, 14", N.2°E., 20 links, 13.20 feet	t
Description of corner evidence found:	
Basswood Sprouts, 10" - 12", S.36°E., 9 fe Stump Hole, N.2°E., 13 feet - 14 feet Local Evidence: 1½" x 4" iron pipe in lar 4" x 4" x 30" rotted post	ge mound of stone with
Description of monument and accessories I establish	ed to perpetuate the location of this corner:
Placed a 2" x 36" aluminum monument with t T35N, R15E, S15, 1, S22, 1983, RLS-1558 From which the following bear: Sugar, 14", N.28°E., 30.41 feet Sugar, 6", S.45°W., 24.29 feet Basswood, 12", N.43°W., 23.05 feet Steel Sign Post, Southwest, 2.80 feet	milo E- STEFAN S-1558 RHINELANDER, WIS.
Section 22 Signature Mile (County Surve Surveyors Registr Office of Registre I hereby certify to 12th on the 12th	Misconsin, this day of L. Stefan Title Land Surveyor yor, Registered Land Surveyor, or other duly authorized official) ration No. RLS-1558 ister of Deeds County of Forest hat the within instrument was filed in this office for record day of September 19 83, and was filed in Book Page No. of County Records.