	CERTIFIED LAND CORNER RESTORATION	
	OLIVITED LYND COMMENT RECTONNITION	
State of Wisconsin	} ss.	
County of Forest		
Tana Ti Danamin de	. • • • • • • • • • • • • • • • • • • •	٠
I Jean F. Resvick I found evidence of the No.	do hereby certify that on the 23rd day of June, 1 orthwest Section corner of Section 25	9 05
Township 35 North	Range 15 East Fourth Principal Meridian, as de	
hereon; and that from this evi petuate the original location of	idence I established a new monument and accessories as described hereon this corner:	to per-
Description of original monume	ent and accessories and subsequent restorations:	
Surveyed in 1859 by Jame	es McBride	
80.00 chains north betwee Hemlock 8", N.17 W., 26	een Sec. 25 and 26 set wood post	. \\
Hemlock 30", N.52°E., 57	,	_
Hemlock 10", S.37°E., 40	0 lks.	 ,
Elm 12", S.77°W., 40 lks	S.	
		, , ,
-	accessories I established to perpetuate the original location of this corner:	
inside diam. galvanized Replace the south witnes 30 ins. long, 6 ins. above Replaced the north witnes 5 ft. long, filled with cap marked: R15E	ction corner as located from the witness posts set 2 ins. iron pipe, 30 ins. long, 6 ins. below surface of road. ss post with 2 in. inside diam., galvanized iron pipe, ove ground from which the corner is 33 ft. north. ess post with a 2 in. inside diam., galvanized iron pipe, concrete, flanged at bottom, 18 ins. above ground, with branches.	3.5.5
inside diam. galvanized Replace the south witnes 30 ins. long, 6 ins. above Replaced the north witnes 5 ft. long, filled with cap marked: V.C.	ction corner as located from the witness posts set 2 ins. iron pipe, 30 ins. long, 6 ins. below surface of road. ss post with 2 in. inside diam., galvanized iron pipe, ove ground from which the corner is 33 ft. north. ess post with a 2 in. inside diam., galvanized iron pipe,	3.5.S
inside diam. galvanized Replace the south witnes 30 ins. long, 6 ins. above Replaced the north witnes 5 ft. long, filled with cap marked: RISE Constant From which the yellow birch	ction corner as located from the witness posts set 2 ins. iron pipe, 30 ins. long, 6 ins. below surface of road. ss post with 2 in. inside diam., galvanized iron pipe, ove ground from which the corner is 33 ft. north. ess post with a 2 in. inside diam., galvanized iron pipe, concrete, flanged at bottom, 18 ins. above ground, with brace of concrete and scribed bearing trees bear th 7", N.53°W., 12.50 ft. or 18.94 lks.	2.5.5
inside diam. galvanized Replace the south witnes 30 ins. long, 6 ins. above Replaced the north witnes 5 ft. long, filled with cap marked: R15E	ction corner as located from the witness posts set 2 ins. iron pipe, 30 ins. long, 6 ins. below surface of road. ss post with 2 in. inside diam., galvanized iron pipe, ove ground from which the corner is 33 ft. north. ess post with a 2 in. inside diam., galvanized iron pipe, concrete, flanged at bottom, 18 ins. above ground, with brace of collowing blazed and scribed bearing trees bear	3.S.S
inside diam. galvanized Replace the south witnes 30 ins. long, 6 ins. above Replaced the north witnes 5 ft. long, filled with cap marked: RISE Constant Series From which the yellow birch	ction corner as located from the witness posts set 2 ins. iron pipe, 30 ins. long, 6 ins. below surface of road. ss post with 2 in. inside diam., galvanized iron pipe, ove ground from which the corner is 33 ft. north. ess post with a 2 in. inside diam., galvanized iron pipe, concrete, flanged at bottom, 18 ins. above ground, with brace of concrete and scribed bearing trees bear th 7", N.53°W., 12.50 ft. or 18.94 lks.	3.SS
inside diam. galvanized Replace the south witnes 30 ins. long, 6 ins. above Replaced the north witnes 5 ft. long, filled with cap marked: R15E	ction corner as located from the witness posts set 2 ins. iron pipe, 30 ins. long, 6 ins. below surface of road. ss post with 2 in. inside diam., galvanized iron pipe, ove ground from which the corner is 33 ft. north. ess post with a 2 in. inside diam., galvanized iron pipe, concrete, flanged at bottom, 18 ins. above ground, with brace of concrete and scribed bearing trees bear th 7", N.53°W., 12.50 ft. or 18.94 lks.	ass
inside diam. galvanized Replace the south witnes 30 ins. long, 6 ins. above Replaced the north witnes 5 ft. long, filled with cap marked: RISE	ction corner as located from the witness posts set 2 ins. iron pipe, 30 ins. long, 6 ins. below surface of road. ss post with 2 in. inside diam., galvanized iron pipe, ove ground from which the corner is 33 ft. north. ess post with a 2 in. inside diam., galvanized iron pipe, concrete, flanged at bottom, 18 ins. above ground, with brace following blazed and scribed bearing trees bear th 7", N.53°W., 12.50 ft. or 18.94 lks. th 4", N 80°E., 6.58 ft. or 9.97 lks.	
inside diam. galvanized Replace the south witnes 30 ins. long, 6 ins. above Replaced the north witnes 5 ft. long, filled with cap marked: RISE	ction corner as located from the witness posts set 2 ins. iron pipe, 30 ins. long, 6 ins. below surface of road. ss post with 2 in. inside diam., galvanized iron pipe, ove ground from which the corner is 33 ft. north. ess post with a 2 in. inside diam., galvanized iron pipe, concrete, flanged at bottom, 18 ins. above ground, with brace of concrete, flanged and scribed bearing trees bear th 7", N.53°W., 12.50 ft. or 18.94 lks. th 4", N 80°E., 6.58 ft. or 9.97 lks. Resident witnesses	
inside diam. galvanized Replace the south witnes 30 ins. long, 6 ins. above Replaced the north witnes 5 ft. long, filled with cap marked: 1 S24 1 S25 yellow birch yellow birch	ction corner as located from the witness posts set 2 ins. iron pipe, 30 ins. long, 6 ins. below surface of road. ss post with 2 in. inside diam., galvanized iron pipe, ove ground from which the corner is 33 ft. north. ess post with a 2 in. inside diam., galvanized iron pipe, concrete, flanged at bottom, 18 ins. above ground, with brace of concrete, flanged and scribed bearing trees bear th 7", N.53°W., 12.50 ft. or 18.94 lks. th 4", N 80°E., 6.58 ft. or 9.97 lks. Resident witnesses	A.
inside diam. galvanized Replace the south witnes 30 ins. long, 6 ins. above Replaced the north witnes 5 ft. long, filled with cap marked: RISE	ction corner as located from the witness posts set 2 ins. iron pipe, 30 ins. long, 6 ins. below surface of road. ss post with 2 in. inside diam., galvanized iron pipe, ove ground from which the corner is 33 ft. north. ess post with a 2 in. inside diam., galvanized iron pipe, concrete, flanged at bottom, 18 ins. above ground, with brace e following blazed and scribed bearing trees bear th 7", N.53°W., 12.50 ft. or 18.94 lks. th 4", N 80°E., 6.58 ft. or 9.97 lks. Resident witnesses Dated at Rhinelander 19.65. Signature F. Resvick Title Cadastral Survey	yor
inside diam. galvanized Replace the south witnes 30 ins. long, 6 ins. above Replaced the north witnes 5 ft. long, filled with cap marked: R15E	ction corner as located from the witness posts set 2 ins. iron pipe, 30 ins. long, 6 ins. below surface of road. ss post with 2 in. inside diam., galvanized iron pipe, ove ground from which the corner is 33 ft. north. ess post with a 2 in. inside diam., galvanized iron pipe, concrete, flanged at bottom, 18 ins. above ground, with brace of concrete, flanged and scribed bearing trees bear th 7", N.53°W., 12.50 ft. or 18.94 lks. th 4", N 80°E., 6.58 ft. or 9.97 lks. Resident witnesses	yor
inside diam. galvanized Replace the south witnes 30 ins. long, 6 ins. above Replaced the north witnes 5 ft. long, filled with cap marked: R15E	ction corner as located from the witness posts set 2 ins. iron pipe, 30 ins. long, 6 ins. below surface of road. ss post with 2 in. inside diam., galvanized iron pipe, ove ground from which the corner is 33 ft. north. ess post with a 2 in. inside diam., galvanized iron pipe, concrete, flanged at bottom, 18 ins. above ground, with brace e following blazed and scribed bearing trees bear th 7", N.53°W., 12.50 ft. or 18.94 lks. th 4", N 80°E., 6.58 ft. or 9.97 lks. Resident witnesses Dated at Rhinelander 19.65. Signature Jean F. Resvick Title Cadastral Surve (County Surveyor, Registered Land Surveyor, or other duly authorized offic Surveyors Registration No. S-802	yor ial)
inside diam. galvanized Replace the south witnes 30 ins. long, 6 ins. above Replaced the north witnes 5 ft. long, filled with cap marked: S21	ction corner as located from the witness posts set 2 ins. iron pipe, 30 ins. long, 6 ins. below surface of road. ss post with 2 in. inside diam., galvanized iron pipe, ove ground from which the corner is 33 ft. north. ess post with a 2 in. inside diam., galvanized iron pipe, concrete, flanged at bottom, 18 ins. above ground, with brace e following blazed and scribed bearing trees bear th 7", N.53°W., 12.50 ft. or 18.94 lks. th 4", N 80°E., 6.58 ft. or 9.97 lks. Resident witnesses Dated at Rhinelander 19 65 Signature Jean F. Resvick Title Cadastral Surve (County Surveyor, Registered Land Surveyor, or other duly authorized offic Surveyors Registration No. S-802 Office of Register of Deeds County of Forest	yor ial)
Replace the south witnes 30 ins. long, 6 ins. above Replaced the north witnes 5 ft. long, filled with cap marked: S24 From which the yellow birch yellow birch yellow birch	ction corner as located from the witness posts set 2 ins. iron pipe, 30 ins. long, 6 ins. below surface of road. ss post with 2 in. inside diam., galvanized iron pipe, ove ground from which the corner is 33 ft. north. ess post with a 2 in. inside diam., galvanized iron pipe, concrete, flanged at bottom, 18 ins. above ground, with brace e following blazed and scribed bearing trees bear th 7", N.53°W., 12.50 ft. or 18.94 lks. th 4", N 80°E., 6.58 ft. or 9.97 lks. Resident witnesses Dated at Rhinelander 19 65 Signature Jean F. Resvick Geounty Surveyor, Registered Land Surveyor, or other duly authorized office Surveyors Registration No. S-802 Office of Register of Deeds County of Forest I hereby certify that the within instrument was filed in this office for on the 17 day of December 19 65, and was filed	yor ial)
inside diam. galvanized Replace the south witnes 30 ins. long, 6 ins. above Replaced the north witnes 5 ft. long, filled with cap marked: RISE C. S24 yellow birch yellow birch	ction corner as located from the witness posts set 2 ins. iron pipe, 30 ins. long, 6 ins. below surface of road. ss post with 2 in. inside diam., galvanized iron pipe, ove ground from which the corner is 33 ft. north. ess post with a 2 in. inside diam., galvanized iron pipe, concrete, flanged at bottom, 18 ins. above ground, with brace e following blazed and scribed bearing trees bear th 7", N.53°W., 12.50 ft. or 18.94 lks. th 4", N 80°E., 6.58 ft. or 9.97 lks. Resident witnesses Dated at Rhinelander 19.65 Signature Jean F. Resvick Geounty Surveyor, Registered Land Surveyor, or other duly authorized office Surveyors Registration No. S-802 Office of Register of Deeds I hereby certify that the within instrument was filed in this office for on the 17 day of December 19.65, and was filed	yor ial)

Township 35 North, Range 15 East, Section 25, Index No. R-21, Page No.

43515230000

U. S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS

This record shall show the location of the corner and shall include all of the following nine elements (asthrough i).

(a) Identify the corner by reference to the U.S. public land survey system.

O - Corner monument restored.


Section corner to Sections 23, 24, 25, and 26, T.35N., R.15E.

REGISTER'S OFFICE
Forest County, Wis.

Received for record this day
of October A.D., 19.86 at
of clock P.M. and recorded
in Vol. Corner Restorations

Page R-2

Register of Deeds



(b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

In 1859, James McBride set post with the following BTs: Hemlock, 8", N.17°W., 26 links; Hemlock, 30", N.52°E., 57 links; Hemlock, 10", S.37°E., 40 links; Elm, 12", S.77°W., 40 links.

In 1965, Jean Resvick found a witness post 33 feet north of centerline of road and a witness post 33 feet south of centerline of road. Also found an 18" scribed Sugar BT stump, S.25°E., 31.0 feet. He placed a 2" x 30" galvanized iron pipe 6" below surface of road in centerline and replaced witness post 33 feet south with a 2" x 30" galvanized iron pipe and replaced witness post 33 feet north with a 2" x 60" galvanized iron pipe.

In 1986, Lee Scheuerman found the corner as per Resvick and made references to it.

(c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)


Describe witness monuments.

114

(d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.

1. 2" \times 30" galvanized iron pipe 6" below surface of road, in centerline, marking the corner location.

- 2" x 60" galvanized iron pipe, Witness Corner, North, 33.0 feet
- 3. 2" x 30" galvanized iron pipe, Witness Corner, South, 33.0 feet
- 4. Sugar, 12", S.47°W., 44.83 feet
- 5. Sugar, 12", N.07°W., 43.82 feet
- 6. Steel Sign Post, South, 33.0 feet



R-21

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

None.

- (f) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpatuated location?
- (2) a found perpetuated location.

(gah) was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

No.

(1) I. Alan D. Harrison
(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature Signature

