CERTIFIED LAND CORNER RESTORATION

State of Wisconsin	•	
County of <u>Forest</u>		•
I found evidence of the Northwe Township 35 North	do hereby certify that on the 5th st Section corner of S Range 15 East Fourth ce I established a new monument and access corner:	ection 34 Principal Meridian, as described
Description of original monument	and accessories and subsequent restorations:	
Surveyed in 1859 by James M post. Elm, 24 ins. diameter Elm, 20 ins. diameter Elm, 18 ins. diameter Elm, 16 ins. diameter	bears N27E, 36 lks. bears S60E, 30 lks.	sections 33 & 34 set wood
Stream, 8 links wide, Description of corner evidence four Found fallen cedar post alo Service location poster on at the bend running east.	running east, bears north 50 links. running northeast, bears west 56 li nd: ng side post point 30 links south o ash dated 4/9/59. Set a point 50 l Measured 56 links west and hit stre otted hardwood stump. Found bark t	nks. f stream. Found Forest inks south of the stream am running northeast.
ਜ਼-	ssories I established to perpetuate the origin from elm stump set a 2 inch inside	
	ed with concrete with a brass cap m	
T35N R15E S 28 S 27 S 33 S 34 S 1969	which the following new blazed and ellow Birch, 9 inch diameter bears lack Ash, 8 inch diameter, S30E, 3. hite Spruce, 11 inch diameter, bear ugar, 4inch diameter, bears N29E, 2 x 4 cedar post SW, 1.8 feet.	N35E, 18.20 feet or 27.57 lk 54 feet or 5.36 lks. s S42W, 19.33 feet or 29.28
S-802		
	Resident witnesses	JEAN F. RESVICK RHINELANDER,
	Dated at Rhinelander Wiscon	sin. this 1/2 th day of 2025
Section 34	19.69 Signature Jean F. Resvick	Title Cadastral Surveyor
	(County Surveyor, Registered Land Surveyor Surveyors Registration No. S-802	
	Office of Register of Deeds Colored I hereby certify that the within instrument on the 22nd day of May	ounty of Forest was filed in this office for record
Corner monument restored	NoPage NoV-13	of County Records.
Township 35 North Range	Signature Lugene States Section 34 Index	Title Register of Deeds