Resident witnesses:	SCONS
Glen Barker	PHILIP T
Jim Claflin ≺	HANSEN ARGONNE, X
	WIS. S-498
	The state of the s
т 3 6 м	SURVE R12E
1 1 2014	1
	·

		36.12
SS	6	1/4- 1- 32'. 62

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION

History of original corner establishment:

Original corner established by Alfred Millard, Government Deputy Surveyor, in 1858. No record of subsequent resurveys. Corner re-established by H.C. Lawrence, Registered Land Surveyor, in 1958. He ran random line south from corner 31, 32, 5, and 6, and at 71.74 chains he was 8.50 chains west of Section Corner 5, 6, 7, and 8. Corrected bearing of line S6045'E. Because of the large departure, he reran this line south and set 1/4 corner at 36.12, proportionate distance. Did not mark any BT's.

Description of corner evidence found:

Recovered 5" cedar post, squared and scribed 1/4-S S5, 1/4-S S6 in fair condition. No BT's were recovered.

Description of monument and accessories I established to perpetuate the original location of this corner.

Replaced 5" cedar post with 2-1/2" x 30" Berntsen A-1 Federal Monument. Aluminum with magnet installed in cap & base. Post projects 6" above ground, cap stamped -S498 T36N R12E Set old post beside new pipe.

NBT's: Cedar 6" N76°E 12.6 links - scribed 1/4 BT.

Cedar 7" $S2^{O}E$ 100.7 links - scribed 1/4 BT. Post and BT's painted blue.

Dated at	Argonne	, Wis., this.	13th	day of	October	, 1975
Signature	Milió Hamen. (County Surveyor, Registered	Title	Registered	Land Surv	ve yor Registratio	on No. S-498
	(County Surveyor, Registered	d Land Surv	eyor, or other duly	y authorized of	fficial)	•
Office of Re	gister of Deeds, County of	Forest			, I hereby certify	that the within
instrument	gister of Deeds, County of was filed in this office for reco	rd on the	16th	day d	ofOctober	, 1975
at 2:30	o'clockP. M.				DOCUMENT NUMBER	107992
Ling.	o'clock Pr. M.	иД		-		