O = Corner monument restored.

Index No.U-7

History of original corner establishment:

Corner established by I.R. Ritter, County Surveyor, in 1931. Robert Thiel, adjacent land owner, states that it was established for previous land owner.

Description of corner evidence found:

Recovered 12" x 3' iron pipe, projecting 8" above ground.

Recovered OBT - Basswood 5" N45°E 15.5 lks, scribed 1/16 BT (now dead).
Y. Birch 8" N52°W 9.8 lks, scribed 1/16 BT.

Description of monument and accessories I established to perpetuate the original location of this corner.

Replaced iron pipe with $l_2^{l_1}$ iron pipe with 2" brass cap, stamped Pipe projects 18" above ground.

NBTs - Sugar 6" S72°W 31 lks, scribed 1/16 BT.

Sugar 6" S15°E 30.4 lks, scribed 1/16 BT.

S498 T36N R12E

Pipe and BTs painted blue.

sc 1/16 \$\frac{\$129}{29}\$
CPI-1976

Dated at Rhinelander , Wis., this 11th	day of June	, 1976
Signature Thilip Hansen Title Registered County Surveyor, Registered Land Surveyor, or other duly Office of Register of Deeds. County of Forest	Land Surveyor Regi y authorized official)	stration No. S-498
Office of Register of Deeds, County of Forest instrument was filed in this office for record on the 28th	day of June	certify that the within 19.76
Lugen States of Dodgs)	DOCUMENT NUMBER	

By.....Deput