108076

Document Number

CERTIFIED LAND CORNER RESTORATION

(Register of Deeds)

History of original corner establishment:

	1.7 <sub>4</sub>	Wiscon		ss.
County of	ַרָּלַ	rest		_ J
I Thoma	s R.	Arnot	t	. do her
certify tha	t on th	e 10t	h	
certify that of September of September of the september o	tembe	31	, 19.7	5, I fo
evidence o	f the	1/4	^ 0. 7	==44+44
corner of	Sect.	rous T	2 & [	
Township.	<u>ル 記</u>	n 	· n.:	lorth, Ka
			h Princip	
as describe				
I establish	ed a ne			
- 40			_	<b>41</b>
		_	rpetuate	the orig
as describe location of		_	rpetuate	tne orig
		_	rpetuate	tne orig
location of	this co	rner.	rpetuate	tne orig
location of	this co	rner.	rpetuate	tne orig
location of Resident w	this co	rner.		tne orig
location of Resident w	this co	rner.		tne orig
location of Resident w	this co	rner.		tne orig
location of Resident w	this co	rner.		tne orig
location of Resident w	this co	rner.		tne orig
location of Resident w	this co	rner.		tne orig
location of Resident w	this co	rner.		tne orig
location of Resident w	this co	rner.		tne orig
location of Resident w	this co	rner.		the orig
location of Resident w	this co	rner.		the orig
location of Resident w	this co	rner.		tne orig
location of Resident w	this co	rner.		the orig

O = Corner monument restored.


## PUBLIC LAND SURVEY MONUMENT RECORD U. S.

INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through 1).

(a) Identify the corner by reference to the U.S. public land survey system. O . Corner monument restored.

> 1/4 corner common to Sections 7 & 12, T36N, R14-13E, 4th P.M., Forest County, WI.



Describe any record evidence, monument evidence, occupational evidence, testimonial evide any other material evidence you considered, and whether the monument was found or placed. (b) evidence or

Original survey by A. Millard, Deputy Surveyor, in 1858.

Original Bearing Trees:


Hemlock 18", N35°W - 62 links


Hemlock 12", S25°E - 39 links

- 1938- Corner position monumented with a 2" diameter x 5' long iron pipe with brass cap by C.E. Walker, County Surveyor. None of his notes are available.
- 1975- The Walker monument was found by Thomas Arnott S-887, and recorded on document No. 108076 on October 28, 1975.
- 1993- I found the 1938 Walker monument he accepted in good condition and established additional accessories below.
- in the pian view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (witness monuments shall be made of concrete, natural stone, Iron orother equally durable material.) (c)
- Show a plan view drawing depicting the relevent monuments and reference ties which is sufficient in detail to enable occurate relocation of the corner monument if the corner monument is disturbed. Indicate north.

Found a 2" diameter iron pipe 5' long with a brass cap (stamped) set by C.E. Walker in 1938.

- 1- 8" Maple-N52°W-118.42 feet
- 2- 8" Maple-N37°E-15.20 feet
- 3- Steel sign post-East-2.23 feet
- 4- 9" Maple-S42°E-5.77 feet 5- 8" Maple-S43°W-5.13 feet





1 4 2	Decoring any motorial	disarahanay balwaan tha	teamtten of the earner or restored or
	ressignished and the	GOOTION Of their career o	OR BERVIOURIV FARIAFAN AF FAMELANII Abad
	by distance and direc	fion. Show the discrepans:	Y ON the Dian view drawing under (d).
	above. Show the dista	nose betsen the serner us	previously restored or residutished
	and (i) the corner as	restored or reastablishe	d, and (2) to at least 2 of the witness
	monuments shown on the	e drawing in (d), above.	

None

- (f) Was the corner restored through acceptance of (i) an obliterated evidence location, or, (2) a found perpetuated location ?
  - (2) A found perpetuated location.

(g & h) Was the corner reestablished through last corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

No

(1) 1. John R. Garske, S-1685

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

JOHN R. GARSKE

S - 1685

IRONWOOD

MICHIGAN

SURVEYOR

Signature

Date

CERTIFICATE READY FOR FILING:

District Ranger