CERTIFIED	LAND CORNER	RESTORATION
-----------	-------------	-------------

Index No. N. N. 2.3

History of original corner establishment:

Original subdivision by James L. Nowlin June 2 - June 12, 1965

Hemlock 20 N60E 20 Lks. Sugar 8 S60W 15 Lks.

Description of corner evidence found:

2" iron pipe 5' long with brass cap set by C.E. Walker in 1938

Description of monument and accessories I established to perpetuate the original location of this corner.

Left monument set by Walker

Ties:

Maple 6" S79W 18.18 feet Maple 8" N14E 87.30 feet monument on south line of pipe line.

THOMAS R.
ARNOTT
S-887

WIS.
SURVENIEND SURV

Dated at <u>Crandon</u>	., Wis., this	28	3th	day of	Octobe	L 	1975
Signature Thomas R. Alio	Title.	Land	Surv	eyor		Registrati	on No. S-887
(County Surveyor, Registere	ed Land Surv	eyor, or o	ther duly	y authorized of	ncial)	3	
Office of Register of Deeds, County of	Fore	st			I he	reby certif	v that the within
instrument was filed in this office for reco	ord on the	281	th	day o	f Octob	er	y that the within 19.75
at	•			-	•		•
	•	•		_			108081
Ingene Dallyn	Ц			Documer	at Numb	er.	

By......Deputy