State of Wisconsin

I Thomas R. Arnott, do hereby

certify that on the 5th day

of December, 19.75, I found

evidence of the 1/4

corner of sections 25 & 36

County of Forest

SS.

O = Corner monument restored		= Corner	monument	restored
------------------------------	--	----------	----------	----------

CERTIFIED LAND CORNER RESTORATION

Index Nb.

History of original corner establishment:

Original subdivision by James L. Nowlin June 2 - June 12, 1865

Birch Sugar 30 8

N32W S60E 15 Lks. 18 Lks.

Description of corner evidence found:

2" iron pipe 5' long with brass cap set by G.E.Walker in 1938

Description of monument and accessories I established to perpetuate the original location of this corner.

Left monument set by Walker

Ties:

Maple Y. Birch 6 12 N36E S46E

4.74 feet 13.05 feet

Dated atCrandon	, Wis., this	15th	day of	December,	1975

Signature Thomas Acus Title Land Surveyor Registration No. S-887.

(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Forest, I hereby certify that the within instrument was filed in this office for record on the 15th day of Becember, 19.75.

at 11.0'clock M.

108378


Register of Decks)

Document Number

By....Deputy

Document Number

189321



U.S. PUBLIC LAND SURVEY MONUMENT RECORD

(AS REQUIRED BY S. A-E 5.02, WI ADM. CODE)

HISTORY OF ORIGINAL CORNER ESTABLISHMENT AND SUBSEQUENT RESTORATIONS AND DESCRIPTION OF ANY RECORD, MONUMENT, OCCUPATIONAL, TESTIMONIAL, OR OTHER EVIDENCE CONSIDERED:

1865 - JAMES NOWLIN, SURVEYOR, SET POST

SET THE FOLLOWING WITNESSES: BIRCH 30" N32"W 15 LINKS SUGAR 8" S60°E 18 LINKS

1938 - C.E. WALKER, SET 2" IRON PIPE 5' LONG WITH BRASS CAP.

1975 - THOMAS R. ARNOTT, SURVEYOR, S-887, FOUND MONUMENT SET BY C.E. WALKER.

SET THE FOLLOWING WITNESSES:

MAPLE 6" N36"E 4.74 FEET

YELLOW BIRCH 12" S46°E 13.05 FEET

CORNER WAS: (CHECK ALL THAT APPLY)

RESTORED THROUGH ACCEPTANCE OF AN OBLITERATED LOCATION

MRESTORED THROUGH ACCEPTANCE OF A FOUND PERPETUATED LOCATION

CONSIDERED A LOST CORNER AND REESTABLISHED THROUGH LOST CORNER PROPORTIONATE METHODS (INCLUDING A PLAN VIEW DRAWING SHOWING DISTANCES AND DIRECTIONS TO OTHER PUBLIC LAND SURVEY CORNERS USED FOR PROPORTIONING AND DETERMINING THE CORNER LOCATION)

□RESTORED OF REESTABLISHED IN A LOCATION THAT DIFFERS FROM A PREVIOUS RESTORATION OF REESTABLISHMENT (INCLUDE A PLAN
VIEW DRAWING AND INDICATE WHAT WAS SET AND/OR FOUND)

DESCRIBE THE MONUMENT AND ACCESSORIES USED TO PERPETUATE THE LOCATION OF THIS CORNER. (INCLUDE A PLAN VIEW DRAWING AND INDICATE WHAT WAS SET AND/OR FOUND)

FOUND 2" IRON PIPE w/BRASS CAP.

FOUND THE FOLLOWING WITNESSES:

SUGAR MAPLE 6" N09°E 16.30 FEET - SET D.H. NAIL IN TREE.
SUGAR MAPLE 12" N47°E 5.37 FEET - SET D.H. NAIL IN TREE.

SET THE FOLLOWING WITNESSES:

SUGAR MAPLE 6" S78"W 18.49 FEET - SET D.H. NAIL IN TREE.
ASPEN 3" S13"E 8.30 FEET - SET D.H. NAIL N TREE.


ALL TREES HAVE CHEST & STUMP BLAZES.

THE SOUTH 1/4


CORNER OF SECTION 25

T. 36 N., R. 13 E.,

FOREST COUNTY, WISCONSIN



= LOCATION OF CORNER



THOMAS M. HEALY R.L.S. 2546

(TYPE OR PRINT NAME) CERTIFY THAT THE CORNER LOCATION SHOWN ON THIS ABOVE RECORD WAS DETERMINED BY ME OR UNDER MY DIRECTION AND CONTROL AND THAT THIS U.S. PUBLIC LAND SURVEY MONUMENT RECORD

IS CORRECT AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF.

1/-17-05 SIGNATURE DATE INDEX No. V-23