Index No.

History of original corner establishment:

Original survey by James L. Nowlin June 2 - June 12, 1865

Birch 14 N60W 16 1ks. Sugar 12 S60E 15 1ks.

Description of corner evidence found:

None; in middle of R.R. Reset post by running lines back from in the city.



Description of monument and accessories I established to perpetuate the original location of this corner.

Set Forest County Alu. Mon. at 1/4 location below R.R. grade.

Ties:

NE cor crossing light control building S85W 29.90 feet Power pole S76E 55.10 feet NW anchor bolt on crossing light S4E 42.60 feet

Dated at	Crandon	, Wis., this	2ad	day of	November	, 19.77
	romes E, Mino	Title	Surveyor	, ·	Registratio	
	(County Surveyor, Regist	ered Land Surve	yor, or other duly	authorized officia	al)	•
Office of Regis	ter of Deeds, County of siled in this office for re	cord on the	orest	day of	, I hereby certify November	that the within
	lock M.	Talin		Doc. No.	112701	
Bv	(Register of Dee	ds)	Deputy			

## Document Number



REGISTER'S OFFICE   Forest County, Wis.
Received for record this and day
95000 clock A M. and recorded in Vol. Corner Restoration
Dage V-07
Kay Sevanson Deputy Register of Deeds

## U.S. PUBLIC LAND SURVEY MONUMENT RECORD

(AS REQUIRED BY S. A-E 5.02, WI ADM. CODE)

HISTORY OF ORIGINAL CORNER ESTABLISHMENT AND SUBSEQUENT RESTORATIONS AND DESCRIPTION OF ANY RECORD, MONUMENT, OCCUPATIONAL, TESTIMONIAL, OR OTHER EVIDENCE CONSIDERED:

1865 - JAMES L. NOWLIN, DEPUTY SURVEYOR, SET POST FOR CORNER AND ESTABLISHED 2 BEARING TREES AS FOLLOWS;

BIRCH SUGAR

14"

N 60W S 60°E 16 LINKS 15 LINKS

1977 - THOMAS R. ARNOTT, SET FOREST COUNTY MONUMENT BY RUNNING LINES BACK IN FROM CITY.

ESTABLISHED THE FOLLOWING WITNESSES:

NE COR CROSSING LIGHT CONTROL BUILDING

S 85W S 76°E

29.90 FEET

42.60 FEET

POWER POLE NW ANCHOR BOLT ON CROSSING LIGHT

S 04°E

55.10 FEET

CORNER WAS: (CHECK ALL THAT APPLY)

SIGNATURE

RESTORED THROUGH ACCEPTANCE OF AN OBLITERATED LOCATION

RESTORED THROUGH ACCEPTANCE OF A FOUND PERPETUATED LOCATION

CONSIDERED A LOST CORNER AND REESTABLISHED THROUGH LOST CORNER PROPORTIONATE METHODS (INCLUDING A PLAN VIEW DRAWING SHOWING DISTANCES AND DIRECTIONS TO OTHER PUBLIC LAND SURVEY CORNERS USED FOR PROPORTIONING AND DETERMINING THE CORNER LOCATION)

RESTORED OF REESTABLISHED IN A LOCATION THAT DIFFERS FROM A PREVIOUS RESTORATION OF REESTABLISHMENT (INCLUDE A PLAN VIEW DRAWING AND INDICATE WHAT WAS SET AND/OR FOUND)

DESCRIBE THE MONUMENT AND ACCESSORIES USED TO PERPETUATE THE LOCATION OF THIS CORNER. (INCLUDE A PLAN VIEW DRAWING AND INDICATE WHAT WAS SET AND/OR FOUND)

FOUND EXISTING FOREST COUNTY MONUMENT AND UPDATED WITNESSES TO REFLECT CHANGES IN LOCATION OF WITNESS FEATURES:

ESTABLISHED THE FOLLOWING WITNESSES:

NE COR CROSSING LIGHT CONTROL BUILDING POWER POLE

NW ANCHOR BOLT ON CROSSING LIGHT

S 88° 02' 37"W S 72' 32' 49"E


29.83 FEET 55.09 FEET

S 06' 13' 17"E

32.69 FEET

S 15° 16′ 39″W

4.42 FEET



V-07

INDEX NO.