CE	ERTIFIED LAND CORNER RESTORATION
State of Wisconsin  County of Forest	S.
I Jean F. Resvick do hereby certify that on the 27 day of April 19 77,  I found evidence of the West Quarter corner of Section 2  Township 36 North Range 14 East Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner:	
Description of original monument	and accessories and subsequent restorations:
Surveyed by James McBride South corrected on west si Cedar 14", N34°W, 11 lks. Cedar 12", S63°E, 7 lks.	in 1859 de of section 2, 40.22 chains, set 1/4 quarter section post.
Description of corner evidence fo	und:
Fallen post, 5" x 5" x 6' and 4" x 4" x 18" very decayed post along side 6' post. From point of these posts, very decayed cedar stumps remains at bearings and distances as called for in original notes. Many blazes and overgrowth on fallen cedar fragments.	
Placed 2" inside diameter,	Section of the sectio
Sec. 2	JEAN F. RESVICK RHINELANDER. WIS.  Resident witnesses
	(County Surveyor, Registered Land Surveyor, or other duly authorized official)  Surveyors Registration No. S-802  Office of Register of Deeds  I hereby certify that the within instrument was filed in this office for record
- Corner monument restored	on the 27th day of June 19.77, and was filed in Book No. Page No. of County Records.  Signature Title Register of Deeds
Township 36 North Rang	ve 14 East Section 2 Index No. C-17 Page No.