UMENT NUMBER	27426 27426

State	OI WISC	0115111	l cc
County of	Forest		} ss. }
of December 25 tablish established as described I established	on the 22 thed 1/4 Section 36 thereon; and ed a new mond dhereon to	2nd , 19.8 5 & 6 urth Princip I that from tonument and	Jorth, Range al Meridian, this evidence d accessories the original
Resident w	itnesses:		
N. Spi	ess		
D. Bro	adbridge		
	T 36N	R14E	
	1	; 	

O = Corner monument restored.

	CERTIF	TED L	AND	COR	NER	RESTO	RATION
U.S.	Public	Land	Su	rvey	Mor	nument	Record

Index No. 2-5

History of original corner establishment:

Original Corner established by James McBride deputy surveyor in 1859 from which Birch 6" bears S36E 61 Lks and Birch 7" N51W 8 Lks

Description of corner evidence found:

No evidence of original or other. Set 1/4 on proportionate method total distance from Section 5-6-31-32 T36 & 37N R14E to Section Corner 5-6-7-8 is 5335.65'. Set 1/4 corner proportional to original distance 5385.60'.

Description of monument and accessories I established to perpetuate the original location of this corner. Set a 2 1/4" Forest County aluminum monument with 3/4" alloy cap stamped. Monument projects 5" above ground.

Marked NBT: Maple 10" 34.34' S76E T36N R14E Maple 8" S49W 12.38 Maple 6" 9.94 N6W 1/4 S6 Sugar 6" 52.99' N44E S-1682 1988


Dated at Rhinelander	Wis., this14th	day of	March	
Signature Jou Barlan (County Surveyor, Registered				
(County Surveyor, Registered	d Land Surveyor, or other du	ly authorized official)		
Office of Register of Deeds, County of	Forest		I hereby certify t	that the within
instrument was filed in this office for reco	rd on the 31st	day of Mar	<u>ch</u>	1989
at. 10:25 o'clock A. M.				
at 10:25 o'clock A. M. aul Aschen Renner (Register of Deeds)				
(Register of Deeds)				


Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

(3&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

T.368 37N R14E





Glen Barker

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct shd complete to the best of my knowledge and belief.

Signarure