O = Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION

Index No.

History of original corner establishment:

Original corner established by James McBride, Deputy Surveyor, in 1859 from which sugar 8" bears N35°W, 7 links and sugar 12" bears S20°E, 25 links.

Corner recovered by Connor Forest Industries surveyor and maintained by foresters for many years.

Description of corner evidence found:

Recovered 5" cedar post, squared and scribed S16, S21, in very poor condition. A 1-1/2" iron pipe was standing beside it. A rock cairn had been built up around the base of both monuments.

Recovered an OBT - Sugar 20" N62°W 27 links Scribing partly visible

Description of monument and accessories I established to perpetuate the original location of this corner.

Replaced old wooden post with 2-1/2" Berntsen A-1 Federal Monument, aluminum, with magnet installed in cap and base. Cap stamped -

Pipe projects 18" above ground. Set old post and iron pipe beside it.

NBT's - Hemlock 9"	_	50 links	Scribed	_		T36N,		R141
Sugar 7"	NO/E 3	2.8 links	Scribed	1/4 R.Í.		1 //.	s	16
Pipe post and BT's painted blue.						T / <del>'</del>		21
							S498	
Dated at Argonne	•••••••••	, Wis., this	26th	day of	January		, 1	9.76
D. 1. 1.	1		1	<b>T</b> 1 0			_	

Signature MULLA Flexible.

Title Registered Land Surveyor Registration No. S-498

(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Forest

instrument was filed in this office for record on the lith day of February 10.76

instrument was filed in this office for record on the 4th day of February 19.76.

at 4:00 o'clock P. M.

DOCUMENT NUMBER 108719

Register of Deeds

By......Deputy