CERTIFIED LAND CORNER RESTORATION

State of Wisconsin	
State of Wisconsin County of Forest	> SS.
I found evidence of the North Township 36 North	on do hereby certify that on the 5th day of April , 19 201 orth Quarter corner of Section 30 , Range 14 East , Fourth Principal Meridian, as described dence I established a new monument and accessories as described hereon to perthis corner:
-	ent and accessories and subsequent restorations: et a wood post and marked Bearing Trees:
Spruce 6". Hemlock 12"	N 48° E 34 links S 21° W 17 links
No record of subseque	nt perpetuations.
Description of corner evidence	
	iron pipe with a 3" x 3" sqaured post alongside. I by Conner Lumber Co. many years ago. Accept pipe as er.
Replace pipe with a 23 identify the corner. Tamarack 9" Hemlock 12" Red Maple 6" Steel Sign Post Established Wisconsin	accessories I established to perpetuate the location of this corner: "" x 60" aluminum pipe monument with a cap stamped to Monument extends 12" above ground. Marked BTs: N 39° E 31.70 feet S 84° W 65.42 feet N 30° W 38.55 feet West 0.5 feet North Zone State Plane Coordianates for corner:
: (7)	RANDY R. B-1897 PRENTICE
Section 30	Resident witnesses Dated at Park Falls Wisconsin, this 12 day of Nov. 19.2014
T 36 N R 14 E	Signature Title P.L.S. (County Surveyor, Registered Land Surveyor, or other duly authorized official)
	Office of REDSTER OF ATTS County of FOREST I hereby certify that the within instrument was filed in this office for record
Corner monument restored	No DENER HATOUT. Page No. R-3 of County Records. Signature Mulliful Muna. Title RESER & OPENS
Township 36 North, Ra	nge 14 East Section 30 Index No. 12, Page No.