| CERTIFIED LAND CORNER RESTORATION | | | | |
|---|--|------------------|--|--------------|
| State of Wisconsin County of Forest | \$S. | • | • | |
| Township 36 North | do hereby certify that on the east Section con Range 15 East ence I established a new monument his corner: | , Fourth Pr | rincipal Meridian, a | s described |
| Description of original monumer | it and accessories and subsequent res | storations: | | |
| Surveyed in 1859 by James 1 North between Sections 21 15, 16, 21 and 22. Sugar, 18 inches, N4W, 21 Sugar, 12 inches, N33E, 41 Birch, 10 inches, S54E, 51 Elm, 24 inches, S74W, 52 1 | and 22, 80.00 chains set post links links links | corner to | sections | |
| Description of corner evidence f | ound: | | | |
| Old scribed post and a 2 in S74W, 52 links, a very lar Other bearing trees fall in | _ , | tones. | | |
| I replaced the iron pipe was feet long with an alumina T36N, R15E, S15, S16, S21, Blazed and scribed the fol Maple, 6 inches, N83E, 6.6 | S22, 1980, S-1107 lowing new bearing trees: 3 feet | um pipe, | 2683088888888888888888888888888888888888 | |
| White Birch, 7 inches, S42 Basswood, 7 inches, S22W, White Birch, 7 inches, S82 | 10.33 feet | | COCHRANE S-1107 HILES, WISCONSIN | |
| | Resident witnesses | | , | |
| Sec. 22 | Dated at Laona 19.80 Signature William B. Cochran (County Surveyor, Registered Lan | Pochrau ie Ti | tle Land Surveyo | <u>r</u> |
| j. | Surveyors Registration NoS-1 | | | |
| | Office of Register of Dee | | NU. | |
| Corner monument restored | No. Page No. Page No. Mu | e of C | 19.80, and was founty Records. | iled in Book |
| Township 36 North Ran | ige 15 East Section 22 | , Index No | N=13, Page N | O |
| | | | | |