Index No. J-5

Ctork No. 26272

DOCUMENT NUMB

U.S. 1	PUBLIC	LAND	SURVEY	MONUMENT	RECORD
--------	--------	------	--------	----------	--------

				U.S.	T
State	of Wisc	onsin	}.ss.	•	
County of	Forest		J		
IJohn certify that	CSchu	lke Second	, do he	reby day	
ofOct	ober	, 19	86, I f	ound	
evidence of corner of	Section.	17			
Township Twelve E	_			-	
as described L'establishe	•				
as described location of	l hereon to				
	-				
Resident wi	tnesses:				
		•••••••	•••••		
			•••••	•••••	•
	:				
				<i>,</i> •	
	Ι,	I		<u> </u> \$	•
	1	i		-	
	1	[1		
	 	;	<u> </u>		
	 	 	· !		
 -	¦ \$ecti	on-1	· 字	- -	
	l	!	1		
	\ 	! 	1		
	<u>;</u>	— — — — — — — — — — — — — — — — — — —	<u>'</u> ·		
	•	1	,		
	1	1	!		

O = Corner monument restored.

History of original corner establishment:

Original corner established in 1859 by William Daugherty U.S. Deputy Surveyor Set wooden post with the following bearing trees:

Tamarack 6" N02°W 47 links Spruce 6" S12°E 21 links

Description of corner evidence found:

Recovered top squared tamarack post. Also recovered the tamarack stump, with scaring visible. Used the recovered stump to restore the corner position.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set 2 1/2" dia. X 5' aluminum magnetic capped monument stamped to identify the corner. Set steel sign post Southwest 1.0 Foot. Blazed, scribed, painted and tagged the following bearing trees:

_	_		
Spruce	5"	S86°W	19.77 feet
Spruce	5"	N20°W	33.40 feet
Spruce	4"	S71°E	2.85 feet
Spruce	4"	S05°W	24.21 feet

Dated at Ludington, Michigan , Wis., this fifth day of	<u>January</u> , 19.87
Signature Signature Title Land Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized of	Registration NoS1665
(County Surveyor, Registered Land Surveyor, or other duly authorized o	fficial)
Office of Register of Deeds, County of Forest and instrument was filed in this office for record on the 24th day of the county o	
at 2:00 o'clock P. M.	•
Daul Aschenbranner	

" Deputy

(Register of Deeds)


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

No discrepancy, first corner restoration.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

The corner was restored through acceptance of found original evidence.

(g&h) was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



John C. Schulke { i } (type or print name) certify that the conner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

January 5th,

Certificate Ready for Filing:

District Ranger

John C.

S - 1665

Ludington