


U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Index No. P-9

State of Wisconsin }
County of Forest } ss.

I, John C. Schulke, do hereby
certify that on the Nineteenth day
of May, 1986, I found
evidence of the East Quarter
corner of Section 20
Township Thirty Seven, North, Range
Twelve East, Fourth Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.

Resident witnesses:



○ = Corner monument restored.

History of original corner establishment:

Original corner established in 1859 by William Daugherty, U.S. Deputy Surveyor.
Set wooden post with the following bearing trees:

Tamarack	12"	N37°E	12 links
Spruce	6"	N79°W	18 links

Description of corner evidence found:

Found decayed remains from the corner post which was identified from a recovered chip
of scribed wood. Also recovered the badly decayed remains of the tamarack bearing,
tree which showed evidence of scarring.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 2 1/2" X 5' aluminum monument, 4 feet in the ground, with an aluminum cap
stamped; T37N, R12E, 1/4, S20, S21, 1986, S-1665. Established the following new
bearing trees which are blazed, scribed, painted, and tagged:

Cedar	7"	N82°E	25.14 feet
Cedar	10"	S04°W	41.28 feet
Cedar	10"	S89°W	37.39 feet
Cedar	12"	N09°W	15.81 feet

Dated at Ludington, Michigan, this thirteenth day of January, 1987.

Signature John C. Schulke Title Land Surveyor Registration No. S-1665
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Forest, I hereby certify that the within
instrument was filed in this office for record on the 11th day of March, 1987
at 3:30 o'clock P. M.

Paul Aschenbrenner
(Register of Deeds)

By _____ Deputy

43712202000



(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

No discrepancy, first corner restoration.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

The corner was restored through the recovery of obliterated original corner evidence.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



(i) I, John C. Schulke
(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

John C. Schulke January 13th, 1987
Signature Date

Survey requested by: Dale Sturge 3/4/87

District Ranger Date