	CERTIFIED LAND CORNER RESTORATION	
State of Wisconsin		
County of Forest	ss.	
I found evidence of the So Township 37 North	day of May 19.69, uthwest Section corner of Section 34.  Range 12 East Fourth Principal Meridian, as described idence I established a new monument and accessories as described hereon to perthis corner:	
Surveyed in 1858 by Al wood post. Yellow Birch 9, N Cedar 10, N78E, 1 Cedar 10, S75W, 2 8.00 chains West	5 1ks. 1 1ks.	
Description of corner evidence	found:	
4x4 scribed cedar post	. Fallen spruce 10" diameter at butt scribed bears N23W, 22 lks. eter scribed, bears S29W, 10 lks.	
32.00 chains east to r 8.00 chains west to e		
I accept this to be th the 4 <b>X</b> 4 scribed post w	accessories I established to perpetuate the original location of this corner:  e best available evidence of this corner and on September 9, 1972  as replaced with a 2 inch inside diameter, galvanized iron pipe th concrete, with brass cap stamped.	
T37N R12E  S33 S34 S4 S3 T36N 1972 S-802	From which the following new blazed and scribed bearing trees bear Cedar 8, N32E, 20.22 feet Cedar 5, S60E, 32.72 feet Cedar 7, S47W, 29.97 feet Set iron sign post 1 foot NE of monument  JEAN F. RESVICK RHINELANDER.	DOCUMENT
	Resident witnesses.	No
Sec. 34	Dated at Rhinelander Wisconsin, this of the day of the 19.72.  Signature Jean F. Resvick Title Land Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized official)	MBER 10%
	Surveyors Registration NoS-802	Ö
	Office of Register of Deeds County of Forest	~2
	I hereby certify that the within instrument was filed in this office for record on the 18th day of October 9:30 AM 19.72, and was filed in Book	
Corner monument restore □ =	No. I Page No.Z-13 of County Records.	•
LJ	Signature Line Laterney Title Register of Deeds	
Township 37 North , Ra	Inge 12 East J, Section 24 Index No. Z-13 Page No. 4 3712: 330000	