318

= Corner monument restored.

115	PURLIC	LAND	SHRVEY	MONUMENT	RECORD
U.S.	PUDLIC	LANU	SURVEI	MONOMENI	RECURD

		•	a \sum_	.ς
Index	No.		L	


State of Wisconsin } ss.	History of original corner establishment: Original Government Survey in 1865 by J.L. Nowlin. North between Sections 17 and 18, at 40.00 chains, set Quarter Section Post, from which the following bear;					
County of Forest I William B. Cochrane , do hereby certify that on the 10th day						
of April 19.91., I found evidence of the West Quarter corner of Section 17. Township 37., North, Range 13. East Fourth Principal Meridian,	Sugar Birch	15" 12"	N18°E N05°W	25 1ks. 40 1ks.		
as described hereon; and that from this evidence	Description of corner evider	nce found:		•		
I established a new monument and accessories as described hereon to perpetuate the original	Found a $13/4$ inch diameter well pipe. No other evidence was recovered.					
location of this corner. Resident witnesses:	I accept the well pipe as the best available evidence for restoring the corner position.					
Dean Young	Old East-West fence line starts approximately 200 feet East of corner.				H311318	
	Description of monument as	nd accessories I	established to perpetua	te the original location of this corne	r.	
	2½ feet in the ground	, with an al	uminum cap stamped	num pipe monument, 3 feet lo ; T37N R13E, 1/4, S17, S18, nd scribed bearing trees bea		
	B. Spruce DBL Balsam Steel Sign Post	10" 13"	S58°E S10°E Northeast	37.49 feet 49.13 feet 1.00 feet		
	East-West fence line starts East of the corner approximately 200 feet.					
SECTION 17	Signature William County Sur Office of Register of Deeds, instrument was filed in this at 10:15o'clock	County of series office for record	and Surveyor, or other duly	rveyor Registration authorized official)		

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

(f) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored from accepted evidence.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



HILES,

WISCONSIN

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

William B. Cochrane Feb. 19, 1992 Signature

Survey requested by; Sul ap 4/2/92
District Ranger Date