
••••	Miles H. Cochrane
	Brian James



O = Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION

COCHRANE

S-1107

HILES,

WISCONSIN

History of original corner establishment:

Surveyed in 1858 by Alfred Millard
West between Sections 5 and 32
80.00 chains Set post corner to sections 5, 6, 31 and 32
Cedar, 12", N 35° W, 14 links
Cedar, 9", N 78° E, 17 links
Hemlock, 22", S 78° E, 13 links
Cedar, 14", S 86° W, 13 links

Description of corner evidence found:

Old fence East and West and an old gravel road North and South I set a position at the intersection of the fence and the center-line of the road. I checked this position with survey measurements to the East and West, and I accept this position above propositionate measurement.

Description of monument and accessories I established to perpetuate the original location of this corner.

At the corner position as described above, I set a 1" inside diameter galvanized iron pipe, 30 inches long, from which the following bear:

A 2½" Berntsen A-1 Federal Aluminum Monument, 30 inches long, bears West 12 feet of the corner with the cap stamped:

T37N, R13E, S5, S6, S31, S32, T36N, 1977, S-1107, REFERENCE CORNER, 12FT

W. Birch, 8", bears N 22° E, 25.34 feet W. Birch 8", bears N 24° W. 32.97 feet

Dated at Hiles	, Wis., this	25 th	day of	November	, 1977
Signature William B. Cochra (County Surveyor, Registered	itled Land Surveyor,	Land or other	Surveyor duly authorized offi	Regist	tration No.S.1107
Office of Register of Deeds, County of	FORE	ST		, I hereby c	ertify that the withi
instrument was filed in this office for reco	rd on the	29th	day of	November	, 19. <b></b>
at 11:30 o'clock A. M.  Register of Deeds)				NUMBER 1128	