0
4
0
Q
~~1
0
<del>-</del>
<u> </u>
٠٠,
<del>`</del>

DOCUMENT NUMBER
-----------------

	State of Wisconsin )								
	County of Forest								
	I Glen Barker , do hereby								
	certify that on the 24th day of May , 19 88, I KONTHINK								
est.	rxiderexxxthe Quarter Section								
	corner of 2 & 11  Township 37, North, Range								
	16 Last Fourth Principal Meridian,								
	as described hereon; and that from this evidence								
	I established a new monument and accessories								
	as described hereon to perpetuate the original location of this corner.								
	location of this corner.								
	Resident witnesses:								
	Norm Spiess								
	Herb Wagoner								
	***************************************								
	TZZNI DIJE								
	T37N RI4E								
п	1 • [								
۰									
	. 1 · -1 ·								
	<del>S-</del> - <del>2-</del>								
•									
	1 1/4								
	O = Corner monument restored								

Index No. *E-19* 

History of original corner establishment:

Original corner established by J.L. Nowlin, Deputy Surveyor in 1865 from which Birch 10" bears S20°E 20 links and Sugar 8" bears N22°E 10 links.

Description of corner evidence found:

1" I.P. - S87°W 7.57'

Re-established quarter section corner by proportional measurement. Total distance from previous recovered section corners 2-3-10-11 and 1-2-11-12 is 5220.44'. Set 1/4 corner 2610.22' intermediate.

Description of monument and accessories I established to perpetuate the original location of this corner. Set a  $2\frac{1}{4}$ " aluminum Forest County monument with a  $3\frac{1}{4}$ " alloy cap stamped:

Monument projects 6" above ground.	T37N-R14
Marked N.B.T.'s	1/4 <u>S   2</u>
Balsam 12" N14°W 23.85'	1/4 <u>S 2</u> S 11
Sugar 9" N65°E 71.62'	1988
Reference I.P.	S1682
1" I.P S23°E 7.61'	

	<b>)</b>				
Dated at		, Wis., this	day of		19
Dated at	Barles	Title		Registrati	ion No
(County	Surveyor, Register	ed Land Surveyor, or	other duly authorized of	fficial)	•
Office of Register of Dee	eds County of	Fore	st		y that the within
Office of Register of Dee	this office for rec	ord on the $1$	9th day o	of October	1988
at 11:00 o'clock	.A. M.		•		
Daul Aoch	eubreune	1			
	(Register of Deed	s) .			

By......Deput

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

- (f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?
- (9&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

Proportionate Method

Reestablished 1/4 Corner

2610.22'
2610.22
21
10 11
5220.44'

(i) 1. Glen Barker

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge/and belief.

Date

Juni

Affix Land Surveyor Scal

GLEN
BARKER
S-1682
CRANDON
WI