State of Wisconsin

O = Corner monument restored.

Daniel K. Pleoger , do hereby

certify that on the <u>11th</u> day

Section 34

Township......37. North, Range

14 East Fourth Principal Meridian,

as described hereon; and that from this evidence

County of Forest

CERTIFIED	CORNER	RESTORATION
	COMILIA	NESIGNATION

Index No. Y-14

History of original corner establishment:

Y 1 4

Someone's squared spruce stake bears N71°W 15.00 feet from our position.

Description of corner evidence found:

Corner established by subdivision of the SW 1/4. Location of SW 1/16 is S3-28-58W 1344.334 feet of WC 1/16 and N88-25-36W 1342.50 feet of SC 1/16.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a 1-1/2" iron pipe with 2" diameter brass cap stamped:

Projects 12" above ground.

Marked NBT's:

Black Spruce 6" South 8.07 feet

Black Spruce 6" S82°W 16.98 feet

SW 1/16 S + 34

Scribed 1/16 B.T.

CPI 1981

Dated at	Rhinelander	, Wis., this	24th	day	ofJu	ne	, 19
	Daniel K. Bleoger	Title	Registered	Land	Surveyor		
	(County Surveyor, Regist	tered Land Surve	yor, or other duly	authori	zed official)		
Office of R	egister of Deeds, County of	F	orest		, I	hereby certify that	the within
instrument	was filed in this office for r	ecord on the	lst		lay ofJ	uly	<u>., 19 81</u>
at 8:30 o'clock A. M. (Register of Deeds) Deputy			DOCUMENT NO.				
Bv	(Register of De	eds)	Deputy			120047	