
CEPTIFIED LAND CORNER RESTORATION

	KITTED LAND CORNER RESIGNATION
State of Wisconsin	
County of Forest	
I found evidence of the Northes	do hereby certify that on the 3rd day of June, 1968, Section corner of Section 25, Range 15 East, Fourth Principal Meridian, as described
	ce I established a new monument and accessories as described hereon to per-
	and accessories and subsequent restorations:
North between some solution of the set wood post for the set of th	sections 25 and 30, 80.00 chains for corner to sections 19, 24, 25 and 30. Solutions, Solutions 19, 24, 25 and 30. Solutions 19, 20, 21 lks. Solutions 18, 20, 21 lks.
W. Pine stump b Tamarack stump	nd: ribed cedar post with rusted F. S. Location poster attached. rears S. 13° E., 14.3 ft. from post found. bears N. 65°E., 1.3 ft. from post found. bears S. 52° W., 9.9 ft. from post found.
Natural swamp o	alls check to the North, South and East.
Replaced 4x4 ce	essories I established to perpetuate the original location of this corner: edar post with 2 inch inside diameter galvanized wrought et long, filled with concrete, 1 foot above ground with ed:
T 37N R 15E, R 16E S 24 S 19 S 25 S 30 1968 S-802	From which the following blazed and scribed new bearing trees bear: Tamarack, 7 ins., S. 20° E., 12.20 ft., 18.48 lks. W. Pine, 6 ins., S. 60° W., 11.82 ft., 17.90 lks. Tamarack, 4 ins., N. 58° W., 64.94 ft., 98.39 lks.
	Resident witnesses
	Dated at Rhine lander Wisconsin, this 12th day of June
	19.68. Signature Jean F. Resvick Title Cadastral Surveyor
SEC. 25	Signature Jean F. Resvick Title Cadastral Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized official)
	Surveyors Registration No. 5-802 DOCUMENT NO. 95059
	Office of Register of Deeds County of Forest
	I hereby certify that the within instrument was filed in this office for record
= Corner monument restored	on the 9th day of August 1968, and was filed in Book
	No. I Page No. R-25 of County Records. at 9:45 A.M. Signature Little Register of Deeds
	Signature Title Register of Deeds 15 East , Section 25 , Index No. R-25 , Page No.
Township 37 North Range	
	43715240000

43715240000



U. S. PUBLIC LAND SURVEY MONUMENT RECORD

INSTRUCTIONS

This record shall show the location of the corner and shall include all of the following nine elements (a through i).

(a) Identify the corner by reference to the U.S. public land survey system.

O - Corner monument restored.

Section corner to Sections 19, 24, 25, and 30, T.37N., R.15-16E.

REGISTER'S OFFICE |
Forest County, Wis.

Received for record this day

of A.D. 19.80 at

O.40 o clock A.M. and recorded

In Volcorner Residentions

Register of Deeds

24 19


(b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed. In 1857, Artemas Curtis set wood post with the following BTs: Tamarack, 6", S.52°W., 15 links; Spruce, 5", N.52°W., 7 links; Tamarack, 12", N.65°E., 2 links; White Pine, 12", S.13°E., 21 links.

July 26, 1934, L. M. Gilson found post in good condition and placed a metal location poster on found.post.

June 3, 1968, J. Resvick found 4" x 4" Cedar post (scribed), with rusted Forest Service location poster, southwest of fence corner post. From Cedar post, White Pine stump, S.13°E., 14.3 feet; Tamarack stump, N.65°E., 1.3 feet; Tamarack stump, S.58°W., 9.9 feet. Replaced 4" x 4" post with 2-inch inside diameter galvanized pipe, 5 feet long, filled with concrete with stamped brass cap with the following BTs: Tamarack, 7", S.20°E., 12.20 feet; White Pine, 6", S.60°W., 11.82 feet; Tamarack, 4", N.58°W., 64.94 feet

- (c) In the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (Witness monuments shall be made of concrete, natural stone, iron or other equally durable material.)

 Describe witness monuments.
- (d) Show a plan view drawing depicting the relevant monuments and reference ties which is sufficient in detail to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.
- 1. Spruce, 12", N.48°E., 44.85 feet
- 2. Red Maple, 6", S.49°E., 33.13 feet
- 3. White Pine, 6", S.60°W., 11.52 feet
- 4. Tamarack, 4", N.58°W., 64.94 feet
- 5. Steel Sign Post, North, 4.2 feet
- 6. 2" x 5' iron pipe filled with concrete with brass cap to identify the corner.



37-15

(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

- (f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?
- (2) a found perpetuated location.
- (gan) was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

No.

Alan D. Harrison

lype or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Marson Danson Signature

1/3/86

