ss.

State of Wisconsin

CERTIFIED LAND CORNER RESTORATION

County of Forest		
I found evidence of the South. Township 37 North	Quarter corne , Range 15 East ce I established a new monument and	th day of September, 1981, r of Section 26 Fourth Principal Meridian, as described d accessories as described hereon to per-
Description of original monument	and accessories and subsequent restor	rations:
West on true line between Se 39.75 chains set 皇 section : Fir 6", N44W, 12 links Linn 12", S69E, 22 links	post	
Description of corner evidence for	ınd:	•
3" x 3" x 18" scribed Cedar Basswood stump S69E, 15 fee	post, fallen - from which bea	r a large
Description of monument and acc	essories I established to perpetuate th	e location of this corner:
Placed a 2" x 30" aluminum supported in mound of stone	monument in post hole, 24" in	the ground,
References:		
Sugar Maple 5", East, 1 Sugar Maple 6", S25W, 1 Sugar Maple 6", N43W, 1 Steel Sign Post	1.74 feet	MILO E- STEFAN S-1558 RHINELANDER, WIS.
	•	"MOSURY"
	Resident witnesses	,
Section 26	19.81. Milo E. Stefan	Wisconsin, this 5th day of October Title Land Surveyor Surveyor, or other duly authorized official)
		County of Forest
- Corner monument restored	on the 13th day of Septem No. Page No.	
	Signature Luginit State	Title Register of Deeds Index No. V-19 , Page No.
Township 37 North, Range	2. 15 East Section 26	Index No. V-19 Page No.