


U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Index No. A-21

State of Wisconsin }
County of FOREST } ss.

I, John Schulke, do hereby
certify that on the 25th day
of July, 1989, I found
evidence of the Northeast Section
corner of Section 2
Township 37, North, Range
12 East, Fourth Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.

Resident witnesses:



● = Corner monument restored.

History of original corner establishment:

In 1858, Alfred Millard set a wood post with the following corner references:

Hemlock	10"	N36°W	26 lks.	Hemlock	18"	N15°E	42 lks.
Sugar	14"	S76°E	38 lks.	Sugar	18"	S30°W	87 lks.

Description of corner evidence found:

In 1937, corner determined from the remains of the original bearing trees by the
GLO surveyors. Set a concrete monument with the brass tablet embedded on
top and stamped to identify the corner. The following corner references:

Poplar	6"	N19°E	32 lks.	Maple	10"	S39½°E	75 lks.
Hemlock	12"	S81 3/4°W	52 lks.	Elm	7"	N33½°W	13 lks.

In 1989, John Schulke found monument in place with the following corner references:

Dead Elm	20"	N30°W	8.70 ft.	stump hole	S32°E	49.5 ft.
Hemlock	20"	S84°W	34.02 ft.	stump hole	N12°E	12.5 ft.

Description of monument and accessories I established to perpetuate the original location of this corner.

Set a steel sign post 1.2 feet Northwest of the monument. Blazed, scribed, tagged
and painted the following new bearing trees:

Maple	10"	N12°W	20.75 ft.
Maple	6"	N34°E	17.80 ft.
Maple	11"	S20°E	45.58 ft.

Dated at Wabeno, Wis., this 25th day of October, 1989

Signature John C. Schulke Title Register Land Surveyor Registration No. S-1665
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Forest, I hereby certify that the within
instrument was filed in this office for record on the 8th day of March, 1990
at 1:00 o'clock P. M.

Paul Achenbrenner
(Register of Deeds)

By _____ Deputy

FORM NO. 985-A

H.C. Miller Company
Surveyors & Engineers

Stock No. 26273

DOCUMENT NUMBER

139245

43812350000

e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

No.


(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

(2) a found perpetuated location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?


No.

SECTION CORNER		
S35	S36	T38N
S2	S1	T37N



1. Monument
2. Hemlock 20" S84°W 34.02 ft.
3. Maple 11" S20°E 45.58 ft.
4. Maple 6" N34°E 17.80 ft.
5. Maple 10" N12°W 20.75 ft.
6. Steel sign post NW 1.2 ft.

Affix Land Surveyor Seal



(i) John Schulke (RLS-1665)
(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

John C. Schulke Oct 25th, 1989
Signature Date

Survey requested by: Dale B. Stange 1989
District Ranger Date