Original Government Survey in 1858 by Alfred Millard.

State of Wisconsin
State of Wisconsin State of Wisc
I William B. Cochrane do hereby
of April
evidence of the <u>East Quarter</u> corner of <u>Section 1</u>
Township
as described hereon; and that from this evidence I established a new monument and accessorie
as described hereon to perpetuate the origina
location of this corner.
Resident witnesses:

SECTION	

= Corner monument restored.

Description of corner evidence found:

45 chains enter swamp NW, SE.

Tamarack

Spruce

History of original corner establishment:

Corner area searched by Jean Resvick 6/11/70 No evidence recovered.

North between sections 1 and 6 at 40 chains set post form which:

N35°W

S65°E

Description of monument and accessories I established to perpetuate the original location of this corner.

At proportionate distance and on line between opposing Section Corners. Set a $2\frac{1}{2}$ "X36" aluminum pipe monument $2\frac{1}{2}$ feet in the ground with an aluminum cap stamped: T38N, R13E, S1, S6, R14E, 1992, S-1107. From which the following bear:

42 1ks

29 1ks

Maple	4"	S66°E	25.47 feet
Spruce	18''	S61°W	11.92 feet
Steel sign	post	West	1.00 feet

Dated at	Hiles		Wis., this	4 th	day of.	January		95 , 19
Signature 4	Illiam B.	Cochrane	Title	Land	Surveyor		Registration No	S-11(
8	(County Su	rveyor, Registered	Land Surveyor	or 9th	er duly authorized	official)		
of Regulation of	ister of Deeds vas filed in this clock	County of	d on the	1 23	day	of Aug	Registration No	he with:
	(F	Register of Deeds)						

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.


See drawing below.

(r) was the corner restored through acceptance of (1) an oblicerated evidence location, or, (2) a found perpetuated location?

Re-established through lost corner proportionate methods.

(gkh) Was the corner reestablished through lost corner proportionate mothods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

Steel sign post West 1.00'



Maple 4" S66°E 25.47'

Affix Land Surveyor Scal

WILLIAM B.

COCHRANE

S-1107

HILES,

WISCONSIN

Spruce 18"
S61°W 11.92'

William B. Cochrane

type or print name; certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief

1/4/95

Signature

{ i }

Date