CERTIFIED LAND CORNER RESTORATION

State of Wisconsin		
State of Wisconsin State of Forest County of Forest	S.	
I found evidence of the	do hereby certify that on the lith day of May North Quarter corner of Section 25 Range 13 East Fourth Principal Meridian, as not I established a new monument and accessories as described here	described
petuate the original location of th		
Description of original monument and accessories and subsequent restorations:		
Surveyed in 1865 by H. Now 40.04 chains, set wood post Hemlock, 12", N21°E, 32 lks Sugar, 13", S10°W, 24 lks.	t s., 21.12 feet	
Description of corner evidence for Hemlock Stump (rotted), 12 Stump Hole, Sloow, 16.0 fe Local Evidence: DNR locate Large (26 rock moun	et sion poster on a 4" Sugar at 8 feet off ground. 5" - 28") cull Basswood with beaver blaze facing	
_	ear: et eét feet 80 feet DOCUMENT NO. WIS.	OWS:
	124237	
	Resident witnesses	
	Dated at Rhinelander Wisconsin, this day of	
	19.83. Mils C. Stefan Signature Milo E. Stefan Title Land Survey	
Section 25	Signature Milo E. Stefan Title Land Survey (County Surveyor, Registered Land Surveyor, or other duly authorized o	
	Surveyors Registration No. RIS-1558	
	Office of Register of Deeds County of Forest	
I hereby certify that the within instrument was filed in this office for record on the 15th day of September 19.83 and was filed in Book		
	No	
	Signature Light Section 25 , Index No. R-23 , Page No.	Deeas
Township38 North, Rang		No.
	43813240020	