| <u>Σ</u> | 2627 | | |
|-----------------|------------|--|--|
| HCMillerCompany | Stock No. | | |
| • | . <u>.</u> | | |
| | | | |

| U.S | . PUBLIC LAND SURVEY MONUMENT RECORD | G-17 Index No |
|--|---|---|
| State of Wisconsin } ss. | History of original corner establishment: | |
| County of Forest | The Original Government Survey of the subdivision of the township | |
| Tohn C Sobulko | race done in 1965 by T. T. Nowlin | • |
| I John C. Schulke do hereby | | |
| certify that on the 25th day of May | | REGISTER'S OFFICE (Forest County, Wis. |
| evidence of the Quarter | | REGISTER'S OFFICE (Forest County, Wis. Received for record this. of Exercise A.D., 19.0. |
| corner of 10 and 11 | - - | of Hermun N.D., 19.0.0 O:10o'clock A.M. and record |
| Township38 | | in Vol. CORNER RESTORA |
| 14 East Fourth Principal Meridian, | | |
| as described hereon; and that from this evidence I established a new monument and accessories | | Register of Deeds |
| as described hereon to perpetuate the original | round no evidence | incoloned of part |
| location of this corner. | | |
| | | |
| Resident witnesses: | • | |
| • | | |
| ************************************** | • | |
| | • | |
| | Description of monument and accessories I established to perpetuate the original locati | |
| | Set a 2 1/2" diameter aluminum pipe monument, 5 feet long, 4 feet in the ground, with an aluminum cap stamped: T38N, R14E, 1/4, S10, S11, 1988, S-1665. The monument is placed in a mound of stones 15 feet North of the North side of Popple River Bank. Established the following corner references: Red Maple 9" N69°W 119.34 ft. Red Maple 5" N07°W 145.41 ft. chiseled "X" on Boulder 6'X6' S19°E 78.36 ft. "X" on Boulder 4'X5' N33°W 105.26 ft. Steel sign post West 1.1 ft. Dated at Cable Wis, this 15 th day of Octobe | r, 19.88 |
| | at the Color Man Bookston Land Summore | C_166E |
| 1,0 | Signature Cohn (County Surveyor, Registered Land Surveyor, or other duly authorized official) | Registration No.S-1665 |
| | Office of Register of Deeds, County of Forest | hereby certify that the with |
| [- | instrument was filed in this office for record on the 9th day of De | cember 1988 |
| | at.10:10o'clock | |
| | Jaul Aschere remer (Register of Deeds) | |
| O = Corner monument restored. | ByDeputy | • |

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

None, first corner restoration.


There is a discrepancy in the stream location from the GLO notes which lists a stream flowing East 50 links wide, 7.00 chains (462 feet) North of the corner.

(r) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

See g and h.

(g&h) was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

The corner was restored through proportional methods.



Affix Land Surveyor Scal

SCONS

JOHN C.

SCHULKE

S-1665

LUDINGTON

MI

John Schulke

(i)

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is coffrect and complete to the best of my knowledge and belief.

John C. Lehelle Oct. 15th

Survey requested by

District Ranger

10-25-83 Date