State of Wisconsin

14 and 15, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original

SS.

PHILIP T

HANSEN

ARGONNE.

WIS.

S-498

Resident witnesses:

location of this corner.

Glen Barker / Jim Claflin

SURVE

O = Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION

Index No. N2

History of original corner establishment: Original corner established by Artemas Curtiss, Deputy Surveyor, in 1857 from which yellow birch 12" bears N44°W, 11 links, yellow birch 10" bears N45°E, 25 links, hemlock 20" bears S48°E, and spruce 14" bears S67°W, 50 links.

Corner recovered by Ray Leigh, Consolidated Forester, during cruising and mapping of this area.

Description of corner evidence found:

Recovered 6" squared cedar post in poor condition.

No evidence of OBT's recovered.

Description of monument and accessories I established to perpetuate the original location of this corner.

Replaced 6" squared cedar post with 2-1/2" Berntsen, A-1 Federal Monument, aluminum with magnet installed in cap and base. Pipe projects 18" above ground. Cap stamped - 8498

NBT's - Cedar 7" N54°E 38.8 links scribed SC BT Cedar 6" N73°W 18 links scribed SC BT Cedar 8" S14°E 29 links scribed SC BT

T38N

R
13 18 1
14 Sec. 24 19 1
E

1975

Cedar post set beside new pipe. Pipe, post, and NBT's painted blue.

Dated at Argonne , Wis., this 13th day of January , 19 76.

Signature Milyo Jamen Title Registered Land Surveyor Registration No. S-498 (County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Forest , I hereby certify that the within instrument was filed in this office for record on the 4th day of February , 19 76 at 4:00 o'clock P. M.

DOCUMENT NUMBER 108701

Engene Statesmy (Register of Deeds)

By......Deput

State				
	of W	/isconsin	`	) } ss.
County of	Fore	st		
IWilliand certify that of February ferror of Township L4Eas.t. as described to the certification of	ton the lary	Cochrane 25th ortheast on 24 . Fourth P and that f w monumer n to perpendent.	, 19.85 Section Nor rincipal rom this	th, Range Meridian s evidence
•	)	,=*****		~ 7
. <u>-</u>	1		i	<del></del>
·	)   	i i	i i	*.
<b></b>	       		i i !	· ·
<b></b>	           		i i l	·.
				·.
		T+ON -	24;	·.
		T+ON -	24;	

ed.

History of original corner establishment:

Original Government Survey in 1857 by Artemas Curtis. North between Sections 19 and 24, 80.00 chains, set Section corner post to Sections 13, 18, 19, and 24. From which the following bear:

Cedar	10"	s38°W	40 1ks.
Cedar	7"	N72°W	10 1ks.
Cedar	511	N60°E	20 lks.
Cedar	16"	S27°E	17 1ks.

Description of corner evidence found:

2½" diameter aluminum pipe monument, with an aluminum cap stamped: T38N, R14E, R15E, S13, S18, S19, S24, S-498, 1976, Forest County. From which the following bear:

Cedar 10" N55°E 26.74 feet

No original corner evidence was recovered.

Description of monument and accessories I established to perpetuate the original location of this corner.

Blazed and scribed the following new bearing trees:

Cedar	12"	S31°E	31.78 feet
Cedar	. 4"	s78°W	30.33 feet
Cedar	6"	N58°W	28.46 feet
Steel sig	n post	NE	0.50 feet

Dated at Hiles		dav of	March	1985
Dated at Hiles  Signature William B. Cochrane	resue Land Sur	veyor	Registr	ation No. S-1107
(County Surveyor, Regi	stered Land Surveyor, or othe	r duly authorized of	fficial)	
Office of Register of Deeds, County of instrument was filed in this office for	f Forest 24th	day o	, I hereby cer	tify that the within
at 1:00 o'clock P. M.	•			
Paul Asco	endrance			
(Register of D	eeds)			

......Deput


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

William B. Cochrane March 12, 1985

Signature