		V-11	
Index	No.	A _ ! !	

		U.U.
State	of Wisconsin	,) EE
County of	of Wisconsin Forest	
certify that of	L. Pisoni on the 6th arch 19 he South qua Section 28 38 Fourth Prince hereon; and that from a new monument a hereon to perpetual	89. I found arter North, Range ipal Meridian, this evidence and accessories
Resident wit	nesses:	
		· .
<u> </u>		
1	Ī	; ;
, ,	1 [[
!		-
1	ţ	ı
. 1		I I
 -	SECTION 28	· - ÷
1	L	'
1	, I	i
1	, I I	1
1 1	, 	1 1
· - · · · · · · · · · · · · · · ·	, 	
	, 	

History of original corner establishment: Original Government survey in 1865 by James L. Nowlin. S 89°51'W corrected between Sections 28 and 33, 40.25 chains, set quarter section post to Sections 28 and 33 from which the following bear: $N 32^{\circ}E$ 15 links Fir Fir Description of corner evidence found: No original corner evidence found. On November 4, 1966, Jean Resvick, U.S.F.S. found a 3/4" diameter iron pipe at corner position. On March 6, 1989, I found same 3/4" pipe by 4' long marking corner position. No other evidence found and accepted iron pipe at best available evidence for restoring this corner position. Description of monument and accessories I established to perpetuate the original location of this corner. In place of iron pipe, as described above, set a 2½" diameter aluminum pipe monument, 3 feet long, 33 inches in the ground, with an aluminum cap stamped: T38N, R14E, 1/4, S-28, S-33, 1989, S-1634 from which the following new blazed and scribed bearing trees bear (all measurements taken to a nail in side of tree):

Spruce 8" S 07°E 6.36 feet

Hemlock 14" N 55°W 22.10 feet

Spruce 12" N 06°W 34.93 feet

Steel sign post N 42°E 1.55 feet Steel sign post Dated at Iron River, MI Wis, this 18th day of December 19.89 Signature Nay L. Loone Title Land Surveyor Registration No.S-1634

County Surveyor, Registered Land Surveyor, or other duly authorized official) Office of Register of Deeds, County of Forest law day of September 19.90 at 10:45 o'clock A. M. (Register of Deeds)


Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(f) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored from accepted evidence.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



GARY LEE
PISONI
S-1634
IRON RIVER,
MI

Gary L. Pisoni

(i) 1, [type or print name] certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature Sury I. Finance Dan 19

District Ranger

Survey requested by

Chofr I

Date

1990