.	
חווות	
ر د	
ز	

	of Wisc Forest		ss.
County of Glen Ba	rker		- J
I		12th	, do hereb
.c Decemb	er	19	⁰⁴ . I koun
or establishe kynkykkyk	he	Quarter	
corner of		ons 29 &	
Township 14 Eas			North, Rang pal Meridia:
as described	hereon and	urtii Frinci Lthat from	par Meridia. this evidenc
I established			
as described			_
location of th	is corner.		
Resident wit	nesses:		
	piess		
	undt		•
1. • 11			
-			
	т38	N R14E	
	Т38	N R14E	
	Т38	N R14E	
		N R14E	

O = Corner monument restored.

CERTIFIED LAND CORNER RESTORATION U.S. PUBLIC LAND SURVEY RECORD

Index No. 7-5

History of original corner establishment:

Original corner established in 1864 by James L. Nowlin, deputy surveyor from which birch 12" bears N55E 13 1ks and sugar 8" S79W 20 1ks.

Description of corner evidence found:

Corner re-established by proportionate method. Total distance from section corner 29-30-31-32 to section corner 19-20-29-30 is 5249.04. Set 1/4 corner 2624.52' intermediate.

Set a 2½" A-1 Federal-Forest County monument cap stamped:

Rock cairn around monument.

Marked-NBTs:

Sugar 6" N33W 21.75!

 Iarked-NBTs:

Description of monument and accessories I established to perpetuate the original location of this corner.

Dated at Rhinelander, Wis., this 4th day of February 1985

Signature Title Registered Land Surveyor Registration No.1682

(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Forest , I hereby certify that the within instrument was filed in this office for record on the 22nd day of February , 19.85 at 2:15 o'clock P. ... M.

Paul Aschenbranner
(Register of Deeds)

4, 44


By......Deputy

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below

- (f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?
- (g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

Proportionate method.



Affix Lands Surveyor Scal

GLEN
BARKER
S-1682
CRANDON
WI

OR SURVE DE BEBEUR DE BEBUR DE BEBU

Glen Barker

(i) I.

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature Sau

2/4/85-

()ato

•