	of Wisc		].	ss.
County of	Forest	· <del>-</del>	<b>]</b> `	,
certify that of	L. Pison on the March Sout Sect 38 And a new model hereon to	i hwest ion 33 urth Pri	94, Section North	I found  I found  Range  Ieridian,  evidence cessories
Resident wi	tnesses:			
			•	
•				***********
		· · · · · · · · · · · · · · · · · · ·		
		<u> </u>		
	1 ]	l 	1	
	† 	[   	1	
	<u>;</u> I	i — — —	- <del> -</del> -	
	'   SECTIO	ı PN 3	1 33 ¦	
	i — — — — !	i I	1	
	;	; !	1	
	¦	' –     –	- <u>t</u> -	<b>→ -</b>
	l [	1	1	
	! !	1 <del>1</del>	 	

History of original corner establishment:
Original Government Survey in 1857 by Alfred Millard. West bet. Sections 33 and 4, at 80.00 chs., set Section Corner Post, from which the following bear; Hemlock, 20", N30 W, 18 lks., Hemlock, 18", S43 W, 9 lks., Hemlock, 12", S10 E, 47 lks., Cedar, 10", N63 E, 14 lks.

On 9-28-81 Daniel Pleoger, a Registered Land Surveyor, found 2 old posts, one standing and one down. Also found several old Hemlocks blazed and facing the posts, and 2 location tags. Original calls North fit good. In place of post, set a 2½" dia. aluminum A-1 Federal Monument with an alloy cap stamped; T38N R14E, S32, S33, S4, S5, T37N R14E, S1537, 1981. Blazed and SO2 W Hemlock 22.43 feet scribed the following new bearing trees; S59°W Description of corner evidence found: 38.98 feet Cedar 39.22 feet Cedar  $N40^{O}E$ 12.42 feet Maple

Found monument as described above and the following bearing trees;

Hemlock 18" S02 W 23.18 feet
Cedar 9" S57 W 39.59 feet
Cedar 10" N41 W 39.35 feet
Maple 6" N40 E 12.36 feet

Description of monument and accessories I established to perpetuate the original location of this corner. Set a steel sign post, S47 <sup>O</sup>E, 1.30 feet

Dated at	Iron River, MI		5thday of	May	. 1994
Signature	County Surveyor, Register	Title	Land Surveyor	Regis	tration NoS-1634
J	(County Surveyor, Register	ed Land Surveyo	r, or other duly authorized offici	al)	
Office of Re	egister of Deeds, County of was filed in this office for rec	Forest		I hereby c	ertify that the within
nstrument	was filed in this office for recolock	ord on the	day of	Maich	19. <i>27.</i>

(Register of Deeds)

By glad ballelles Dept


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

None

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(9kh) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location? No



Gary L. Pisoni (i) #. (type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief. Signature Signature

PISONI

S-1634

IRON RIVER,

MI

		CERTIFIED LAND CORNER
State of Wisconsin	} ss.	History of original corner establishmen

Daniel K. Pleoger do hereby certify that on the day of September 19 81, I found evidence of the Section corner of Sections 4, 5, 32, 33 Township 37 & 38, North, Range 14 East Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner. \_\_\_\_\_

County of Forest

Resident witnesses:	PLEOGER S-1537 WINTER, WIS. SURVINOR DE 100000000000000000000000000000000000
<b>*</b> 000	DANIEL
864X	PLEOGER 2 S-1537
DC-30	WINTER, WIS.
	SUR 1 00000000000000000000000000000000000

T37	7N, <u>R</u> 14E.
,S.C.	
<b>—</b> — — —	

O = Corner monument restored.

Original corner established by A. Curtis, Gov. Deputy Surveyor in 1857 from which cedar 10" bears N63E 14 1ks.

Hemlock 20" bears N30W 18 1ks

Hemlock 18" bears \$43W 9 1ks

Hemlock 12" bears S10E 47 1ks

Description of corner evidence found:

Recovered two old cedar posts, squared not scribed, one post standing, other one down. OBT - No visible evidence of any.

Several old hemlocks blazed facing corner position, also two old location tags tacked to nearby trees.

Original calls north between sections 32 & 33 fit good

Description of monument and accessories I established to perpetuate the original location of this corner. Replaced old post with a  $2\frac{1}{2}$  aluminum A-1 federal monument with alloy cap stamped: Monument projects 12" above ground Marked NBTs: T38N R14E

Hemlock 16" S20W 22.43 ft. Cedar 7" S59W 38.98 ft. Cedar 7" N41W 39.22 ft. Maple 4" N40E 12.42 ft. Scribed S.C. - B.T.

T37N R14E S1537 - 1981

Dated at Rhinelander	, Wis., thi	s3	da;	y of <u>Nov</u>	ember		, 1981
Signature Daniel K. Pleager	ノ Title	Registered	Land	Surveyor	Reg	istration No	1537
(County Surveyor, Regi	stered Land Sur	veyor, or other du	ly autho	orized official)	-		
Office of Register of Deeds, County of instrument was filed in this office for at 11:00 o'clock			9th				
(Register of D	eeds)		I	DOCUMENI	NO.	1213	89