	CERTIFIED LAND CORNER RESTORATION
State of Wisconsin Sounty of Forest	ss.
found evidence of the ownship 39 North	, do hereby certify that on the
escription of original monu	ment and accessories and subsequent restorations:
D. Craig. At propor	B59 by William E. Daugherty. Dependent resurvey in 1941 by Hal tionate distance set an iron post, 3 feet long, 2 inches in section corner with brass cap marked: 2, S23, S24, 1941
Cedar 6, bears 1 Cedar 6, bears 1	
escription of corner evidence	ce found:
	t record bearing and distance found iron post d above lying in swamp.
Reset monument from l Blazed and scribed ne	ew bearing tree
Tamarack 5, S57V	V, 51.52 feet
Set iron post 1.0 fee	JEAN F. RESVICK RHINELANDER, WIS.
	Dated at Rhinelander Wisconsin, this 17th day of Oct.
	······ 10 72
Sec. 24	Signature Jean F. Resvick Title Land Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized official)  Surveyors Registration No. S-802
Sec. 24	Surveyors Registration No. S-802  Office of Register of Deeds County of Forest,
Sec. 24  — Corner monument resto	Office of Register of Deeds  I hereby certify that the within instrument was filed in this office for record on the 18th day of October  No. I Page No. P-21 9:30 AM County Records.
Corner monument restor	Surveyors Registration No. S-802  Office of Register of Deeds  I hereby certify that the within instrument was filed in this office for record