I William B. Coch	rane do hereby
certify that on the	
of August	_
evidence of the East of	
corner of Section	
Township39	, North, Range
13 East, Fou	rth Principal Meridian
as described hereon; and	that from this evidence
I established a new mor	nument and accessories
as described hereon to	perpetuate the original
location of this corner.	

Resident witnesses:	
	······································

	1	 	1
	] [	<b>!</b> !	] , [
	i I	i	<del>;-</del>
	! ! SECT:	! ! <u>ON_21</u>	1
	i — — — — — — — — — — — — — — — — — — —		1
, 	   <u> </u>	! ! !	 

= Corner monument restored.

## CERTIFIED LAND CORNER RESTORATION

	P-13	
Index	No.	

History of original corner establishment:

Original Government Survey by William E. Daugherty in 1865.

At 40 chains North between sections 21 and 22, set post. From which:

S51°W 14 1ks Sugar N48°E 22 1ks Lynn

Description of corner evidence found:

No original corner evidence was found. No other corner evidence found.

I reestablish the corner position at proportionate distance and line between the the Northeast and Southeast section corners.o section 21.

Description of monument and accessories I established to perpetuate the original location of this corner.

At the corner position, set a.  $2\frac{1}{2}$ "X36" aluminum pipe monument  $2\frac{1}{2}$  feet in the ground with an aluminum cap stamped: T39N, R13E, 1/4, S21, S22, 1994, S-1107 From which:

Maple S76°E 31.77 feet S 5°W 32.08 feet Maple 1.00 feet Steel sign post Southeast

Dated at	Wis., this.	13 tł	1 day of	December ·	. 19
Signature William B. Coch (County Surveyor, Registere	raucite	Land	Surveyor	Registration No.	S-1107
(County Surveyor, Registere	ed Land Surve	yor, or	ther duly authorized o	official)	***************
Office of Register of Deeds, County of instrument was filed in this office for recount 2.30 o'clock M.	Fol	est	<i>S</i>		the within
instrument was filed in this office for reco	ord on the		334 day	of Cuallat	19.96
at 2:30 o'clock M.			•		

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as proviously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.


See drawing below.

Survey requested by:

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Re-established through lost corner proportionate methods.

(gkh) Was the corner reestablished through lost corner proportionate mothods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



District Ranger

Date