7	
1	
Š	
•	
į	
4	
₹	

! 5	PURI IC	ΙΔΝΩ	SHRVEY	MONUMENT	RECORE
<b>び. つ.</b>	PUBLIC	LAND	SOUAFI		<b>NECONE</b>

	U.S.	PUBLIC	LAND	SU
State of Wisconsin County of Forest	n } ss.	Histor	y of origina	al corr
I William B. Coch certify that on the 20th of August	rane do hereby day	Orig Sout	inal Gov h correc to Sect	ted
cvidence of the East Que corner of Section Township 39  14 East Fourth 1	5	•	W. Pine	
as described hereon; and that		Descri	ption of co	rner e
I established a new monume as described hereon to perpe		No c	orner ev	iden
location of this corner.		The	corner p	osit
Resident witnesses:		betw	reen the	Nort
Tony Tillman				
State Plane Co-ordina		Descri	ption of me	onume
N- 265,825.2023 E-2,316,421.2010		$2\frac{1}{2}$ f	he corne eet in t	he g
			Tamarac	· lz
			Tamarac	
	1	•	Steel S	
	<del> </del>			
				Hile
SECTION !	^ <del> </del>	Dated		
	1		ure Will	
			of Register ment was fi	
	1	_	30o'clocl	
		*******	7	Ja

O = Corner monument restored.

ner establishment:

nent Survey in 1865 by William E. Daugherty and Alex McDill. between Sections 4 and 5, at 41.40 chains, set Quarter Section 4 and 5, from which the following bear;

25" N40°W 17 1ks. S40°E 43 1ks. 25"

evidence found:

nce was recovered.

tion is re-established at proportionate distance and on line theast and Southeast Section Corners of Section 5.

nent and accessories I established to perpetuate the original location of this corner.

osition, set a  $2\frac{1}{2}$  inch diameter aluminum pipe monument, 3 feet long, ground, with an aluminum cap stamped; T39N, R14E, 1/4, S4, S5, 1986, ich the following new blazed and scribed bearing trees bear;

Tamarack	12"	S80°W,	101.70 feet
Tamarack	12"	N31°W .	93.09 feet
Steel Sign	Post	West	0.50 feet

Dated at	Hiles	, 1	Wis., this	11th	day of	February	19 <sup>.87</sup>
							ation No. S-1107
	(County Su	rveyor, Registered	Land Surveyo	r, or other duly	authorized o	official)	
-		•				•	rtify that the within
instrument w	as filed in this	s office for record	l on the	11th.	day d	of March	19.87
at 3:30 o'c				•	-		
	Dank	Aschent	Renner	·		·	
	(I	Register of Deeds)	•				


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

This corner position was re-established using State Plane Co-ordinates computed from Aerial Photography and a Global Positioning Satellite Survey. The computed corner position was located in the field using a North Seeking Gyro, an Electronic Distance Meter and/or a steel tape.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

William B: Cachrane February 11, 1987
Signature

 $\mathcal{O}$ 

Survey requested by;

(i)

Date

District Ranger