132	
NUMBER	
COMENT	

U.S.	PUBLIC	L.AND	SURVEY	MONUMENT	RECORD

	n ó
Index No.	P-9

State o			} ss.	*
County of	Forest	· · · · · · · · · · · · · · · · · · ·	}	
certify that or of Octobe of Corner of Cownship Last described he ocation of this ocation of this	the East	2nd , 19 st Quarte tion 20 urth Prince l that from onument a		
Resident witne	esses:			
David Brown	ne11			
Tony Tillma				
State Plan N- 250,00 E-2,316,64	e Co-or 9.9836	dinates		
]       	-	         	 	
       	SECTI	і і ри 20		
		i		
		' ] ]	1       	
Corner n	nonument	restored	<u>.l.</u> ,	

History of original corner establishment:

Original Government Survey in 1865 by William E. Daugherty and Alex McDill. North between Sections 20 and 21, at 40.00 chs. set Quarter Section Post to Sections 20 and 21, from which the following bear;

16 1ks. N62°E Tamarac N40°W 15 1ks. Tamarac

Description of corner evidence found:

Found 5" x 5" Wood Post, from which a scribed Tamarac stump bears N40°W, 17.25 feet. It is not known who set the post or made the bearing tree. Distance does not fit the original record.

I accept the wood post as the best available evidence for restoring the corner position  $\Sigma$ 

Description of monument and accessories I established to perpetuate the original location of this corner.

In place of 5" x 5" Wood Post, set a  $2\frac{1}{2}$  inch diameter aluminum pipe monument, 5 feet long, 4 feet in the ground, with an aluminum cap stamped; T39N R14E, 1/4, S20, S21, 1986, S-1107. From which the following new blazed and scribed bearing trees bear;

26.29 feet 2½"x5 Reference Monument 17.25 feet 1.00 feet N40°W Tamarack(Stump) Steel Sign Post

From the Reference Monument, a Steel Sign Post bears NW, 1.00 feet

Dated at	Hiles	, Wis., this	2/th	day of	January	19.07
Signature 4	County Surveyor, Regist	aul Title	Land	Surveyor	Registra	tion No. S-1107
Office of Regi	ster of Deeds, County of as filed in this office for relock	Forest	11th	ily authorized on	I hereby certi	ify that the within
at3:30	lock P. M.	ecord on the		ay o		
	Paul Aschensia (Register of De					
n		-	Danue			


Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored from accepted evidence.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



Affix Land Surveyor Scal

CONS

WILLIAM B.

COCHRANE

S-1107

HILES,

WISCONSIN

SURPRESENTATIONS

SUR

(i) I. William B. Cochrane

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Survey requested by;

Signature

District Ranger

Date