-	į
1	
W. actoratio	
Ultrabally Wilder	7
	_

UMENT

	Township 39 North, Range
	14 East Fourth Principal Meridian, as described hereon; and that from this evidence
	I established a new monument and accessories
	as described hereon to perpetuate the original
	location of this corner.
	Resident witnesses:
	David Brownell
	-**
١	State Plane Co-ordinates
	N- 239,419.9930

State of Wisconsin

County of Forest

I William B. Cochrane , do hereby

certify that on the 30th day

evidence of the East Quarter

corner of Section 31

SS.

E-2,311,9	99.3590		
	` 	t	
	• 	! 	
	i — — — I	;	i
	I SECTIO	i N 31	
		i — — - !	
	 	! !	
	i — — — — — — — — — — — — — — — — — — —	i — — i	
		[

O = Corner monument restored.

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Index No.	X-5
-----------	-----

History of original corner establishment:

Original Government Survey in 1865, by William E. Daugherty, and Alex McDill. North between Section 31 and 32, 40.00 chains, set Quarter Section Post to Sections 31 and 32, from which the following bear;

Tamarac	10"	N10°W	19	lks.
Tamarac	10"	S85°E	23	lks.

Description of corner evidence found:

Found 1" diameter iron pipe, $2\frac{1}{2}$ feet above the ground.

I accept the iron pipe as the best available evidence for restoring the corner position.

No original corner evidence was recovered.

Description of monument and accessories I established to perpetuate the original location of this corner. In place of iron pipe, set a $2\frac{1}{2}$ " diameter aluminum pipe monument, 5 feet long, 4 feet in the ground, with an aluminum cap stamped; T39N, R14E, 1/4, S31, S32, 1985, S-1107. From which the following new blazed and scribed bearing trees bear;

Cedar	13"	S72°E	39.80 feet
Tamarack	9"	s 8°W	63.08 feet
Steel Sign	Post	NE	4.00 feet

ated at	Hiles	, Wis., this	27th	day of	January	, 19
gnature 4	William B. Coc	hrane_Title	Land	Surveyor	Regis	tration NoS-1107
	(County Surveyor, Re	egistered Land Surveyor,	or other	duly authorized o	official)	
ífice of Re	gister of Deeds, County	of Forest			I hereby c	ertify that the withir
strument 3:30	gister of Deeds, County was filed in this office for clock P. M.	or record on the	11th	day	of March	, 198.7
	Paul A	chenblerne	2			
	(Register of	Deeds)				
v			Den	ii t v		


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(r) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored from accepted evidence.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



(i) I, William B. Cochrane
(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

William B. Cochrone October 7 1986

Survey requested by, Large Agen 3-9-8/

District Ranger

Date



U. S. PUBLIC LAND SURVEY MONUMENT RECORD


INSTRUCTIONS:

This record shall show the location of the corner and shall include all of the following nine elements (a through 1).

Identify the corner by reference to the U.S. public land survey system.

O = Corner monument restored.

Quarter Corner common to Sections 31 and 32, T39N, R14E, Forest County, Wisconsin



(b) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed. Original Government Survey in 1865 by William E. Daugherty and Alex McDill.

In 1985, William B. Cochrane, Land Surveyor with the Forest Service, found a l" diameter iron pipe 2 feet above ground. In place of iron pipe, set a $2\frac{1}{2}$ " diameter aluminum pipe monument, 5 feet long, 4 feet in the ground, with an aluminum cap stamped; T39N, R14E, 1/4, S31, S32, 1985, S-1107. Blazed and scribed the following;

> Cedar Tamarack

13" 9". S72°E

39.80 feet

SO8°W

63.08 feet

Steel Sign Post

Northeast

4.00 feet

On 7-29-99, Gary L. Pisoni, RLS, found the monument as described above, found the bearing trees as described below, and made a new bearing tree as described below.

See previously recorded Land Corner Certificate, Document # 132396.

- (c) in the plan view drawing below, provide reference ties to at least 4 witness monuments, or, if the location is within a municipality, to at least 2 witness monuments. (witness monuments shall be made of concrete, natural stone, Iron orother equally durable material.)
- (d) Show a plan view drawing. depicting the relevent monuments and reference tles which is sufficient in detail . to enable accurate relocation of the corner monument if the corner monument is disturbed. Indicate north.
 - 1. Cedar, 16", S72°E, 39.80 feet
 - 2. Tamarack, 12", S08°W, 63.08 feet
 - 3. Steel Sign Post, Northeast, 4.00 feet
 - 4. Tamarack, 14", NO6°E, 45.41 feet(NBT)

REGISTER'S OFFICE Forest County, Wis. Received for record this diladay of October A.D., 1999 at 10:05 o'clock 1 M. and recorded in Vol. Corner Restoration

4391431200

X-5

(a) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

None

ş

f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location 7

Found perpetuated location.

(g & h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

Gary L. Pisoni

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

10-2-99

Signature

(1)

CERTIFICATE READY FOR FILING:

S-1634

IRON RIVER,

MI