CERTIFIED LAND CORNER RESTORATION

State of Wisconsin ss County of Forest			
County of Forest			
I Jean F. Resvick I found evidence of the Norther Township 38 North hereon; and that from this eviden	ast Section , Range 13 East ce I established a new monume	corner of Section 2. Fourth Principal	6 Meridian, as described
petuate the original location of this			
Description of original monument		restorations:	
North between sections 25 at Set post for section corner Birch 10, N67°W, 10 lks. Cedar 14 N22E, 34 lks.	<u>-</u>		
	•		
Description of corner evidence fou	nd:		
Cedar stump, lower blaze with Yellow Birch snag 16 ft. tale 24 inch diameter.	ll, old cat face about 10	inch diameter, tre	
Set point for corner S22°W, Birch snag bears N47W, 10 11	-		
Description of monument and access Set 2 inch diameter galvania brass cap stamped, T38N, Rla from which the following bla Hemlock 18, N24E, 25.24 Ft.	zed iron pipe 5 feet long 3E, S23, S24, S26, S25, 1 azed and scribed new bear	, filled with concress, 972, S-802 ing trees bear.	ete with
White Spruce 10, S3E, 20.59 Hemlock 13, S44W, 41.09 Ft. Cedar 14, N35W, 25.79 Ft. Set steel sign post 1.4 ft.		9 📉	JEAN F. RESVICK RHINELANDER, WIS.
	Resident witnesses		SURVERBER
Sec. 26	Dated at Rhinelander 19.74. Signature Jean F. Resvick		I day of July Surveyor
	(County Surveyor, Registered Surveyors Registration No	Land Surveyor, or other dul	
	Office of Register of Deed	County of	Forest
Corner monument restored	I hereby certify that the within on the 8th day of Aug No.RestorationsPage No	ust 19 74	, and was filed in Book
	Signature	// //	
Township 38 North, Range	, 13 East V, Section 2	6 Index No. R-21	, Page No
-	101223,0000		