FORM NO. 985-A	H.C.Miller Company (T)	26273	
		Š	
S.		lock	

DOCUMENT NUMBER

139267

= Corner monument restored.

U,S.	PUBLIC LA	ND SURVEY	MONUMENT	RECORD	Index No. S-9,10
State of Wisconsin ss.		original corner estal			C. W. L. C. L. C. L. C. L. C. C. L. C.
County of Forest	Corner wa a Regista	as set in 1980 ered Land Surve	by the U.S.F.S. eyor during the	sub-division of Sec	n of William B. Cochrane, tion 28.
I Gary L. Pisoni , do hereby certify that on the 16th day of August , 19.89, I found evidence of the W.C. of the NW 1/16 corner of Section 28 Township 40 , North, Range 12E , Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original	Governmer with an a Spruce Balsam Steel NW Sixt Description	nt Lots 2 and 3 aluminum cap, s 7'' 9''	s and set a $2\frac{1}{2}$ stamped to ident N 33 W. S 81 E. North position is in I	r on West shore of Go inch diameter aluming tify the corner. Con 4.14 feet 3.63 feet 0.5 feet Lake bearing N 87°47	um pipe monument 60" long rner references established:
Resident witnesses:	Black	eferences recov Spruce 8" sign post	vered: N 33 ⁰ W North	4.14 feet 0.5 feet	
		nd scribed the	accessories I establi following new S	bearing tree:	ginal location of this corner.
SECTION 28					August , 19 89
1 1 1	Signature	Jary L. Fisco	Title or, Registered Land Sur	Land Surveyor rveyor, or other duly authorized	Registration No. S-1634
 	Office of Re	gister of Deeds, Co was filed in this off clock	ounty of Fores	t 8th day	of March 19 90
1 1 1		Saul A.	Schen Renne ter of Deeds)		

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

8" Black Spruce N 33°W, 4.14 feet

□ Steel sign post North, 0.5 feet

Witness Corner to NW 1/16 Corner of Section 28, West shore of Lake

7" Hemlock (NBT) S 10°W, 27.63 ft.



Gary L. Pisoni (type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief. (i)

8-26-89

Survey requested by:

District Ranger