CERTIFIED LAND CORNER RESTORATION

	CERTIFIED EARLY CORRECT RECTORATION
State of Wisconsin	
State of Wisconsin County of Forest	> SS.
I found evidence of the North	e, do hereby certify that on the, day of, 19.82, theast Section, corner of, Section 5, Range, Fourth Principal Meridian, as described idence I established a new monument and accessories as described hereon to perthis corner:
Description of original monum	ent and accessories and subsequent restorations:
Original survey in 1859 to Dependent resurvey in 193 From the remains of the o	by William E. Daugherty 9 by H. D. Craig 9 riginal bearing trees, set a concrete monument, 24" long, 6" in and, with a brass tablet stamped T40N, R12E, S32, S33, S5, S4, bear:
Description of corner evidence	found:
Found monument as described Sugar Maple, 23", N82E, 24 Hemlock, 15", S17 ½ E, 36 Sugar Maple, 23", S65 3/4" x 4" Cedar post 0.50 I	2.44 ft. 6.30 ft. 4.W, 56.10 ft.
Description of monument and	accessories I established to perpetuate the location of this corner:
Blazed and scribed the for Hemlock, 21", N41W, 72.12	ollowing new bearing tree: ft. WILLIAM B. COCHRANE S-1107 HILES, WISCONSIN
	124410
	Resident witnesses
***************************************	The first of the f
Section 5	19.82 William B. Cochrane
	Signature William B. Cochrane Title Land Surveyor (County Surveyor, Registered Land Surveyor, or other duly authorized official)
	Surveyors Registration NoS-1107
	Office of Register of Deeds County of Forest I hereby certify that the within instrument was filed in this office for record
- Corner monument restor	7+h
Township 39 North R	ange 12 East Section 5 Index No. A=9 Page No.

44012320000