Stock No.

State of Wisconsin

County of Forest

William B. Cochrane do hereby certify that on the 7th day of August , 19.86 , I found evidence of the North Closing Quarter corner of Section 2 Township...40...., North, Range .13 East Fourth Principal Meridian,

as described hereon; and that from this evidence

I established a new monument and accessories as described hereon to perpetuate the original

Resident witnesses:

location of this corner.

David Brownell

Tony Tillman

O = Corner monument restored.

History of original corner establishment:

NONE

SS.

Description of corner evidence found:

NONE

The corner position was re-established at proportionate distance between the Northwest and Northeast Section Corners of Section 2, and on line between the Standard Quarter Section Corner of Section 35 and the Standard Section Corner common to Sections 35 and 36, T41N R13E.

Description of monument and accessories I established to perpetuate the original location of this corner. At the corner position, set a Railroad Spike flush with blacktop, and stamped: 1/4, S2. From which the following new blazed and scribed bearing trees bear;

Maple Maple

19"

S57°E

81.62 feet 82.19 feet


Hiles. Dated at..... Signature William B. Cochrane Title Land Surveyor Registration No. S-1107
(County Surveyor, Registered Land Surveyor, or other duly authorized official) Office of Register of Deeds, County of Forest I hereby certify that the within instrument was filed in this office for record on the 24th day of February 19.87 at 2:00 o'clock P. M (Register of Deeds)

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

- (f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?
- (g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

| | N89°54'-22"E SC 1/4 | | S35 | S36 | |
|----|---------------------|--------------|--------------|--------------|-------|
| 8 | N89°54'-22''E | S89°52'-23"E | S89°52'-23"E | S89°55'-49"E | |
| S3 | S2 526.54' | 2117.40' | 508.14' | 2135.80' | S2 S1 |

G.L.O. 80.00 chs.



William B. Cochrane Movember 5, 1986 Signature

Certificate ready for filing: Seanch faulty 1/6/87
District Ranger Date