

CERTIFIED LAND CORNER RESTORATION

State of Wisconsin }
County of Forest } ss.

I Jean F. Resvick, do hereby certify that on the 9 day of May, 19 75, I found evidence of the Northeast Section corner of section 33 Township 40 North, Range 13 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner:

Description of original monument and accessories and subsequent restorations:



Surveyed in 1865 by Wm. E. Daugherty
North between sections 33 and 34. 80.0 chains set post corner to sections 27, 28, 33 and 34.
Cedar 10", S27°E, 25 lks.
Cedar 10", N42°W, 16 lks.

Description of corner evidence found:

5x5 scribed cedar post
Cedar snag, bears S27°E, 25 lks. (scribing visible)

Description of monument and accessories I established to perpetuate the location of this corner:

Replaced the post found with a 2 inch inside diameter galvanized pipe, 5 feet long, filled with concrete, with a brass cap stamped:
T40N R13E, S27, S28, S33, S34, 1977, S-802
From which the following bear:
Cedar, 9", N72°E, 34.67 feet
Cedar, 12", S16°E, 20.51 feet
Cedar, 12", S89°W, 33.70 feet
Steel sign post, SW, 0.50 ft.



● - Corner monument restored
□ -

Resident witnesses.....

Dated at Rhineland Wisconsin, this 20 day of July 19 77.

Signature Jean F. Resvick Title Land Surveyor
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Surveyors Registration No. S-802 DOCUMENT NUMBER **113314**

Office of Register of Deeds County of Forest

I hereby certify that the within instrument was filed in this office for record on the 13th day of February 19 78, and was filed in Book No. _____ Page No. _____ of County Records.

Signature Eugene H. Statz Title Register of Deeds

Township 40 North, Range 13 East, Section 33, Index No. V-13, Page No. _____