1324
NUMBER
CUMENT

US	PURI IC	LAND	SURVEY	MONUMENT	RECORE
U.J.	PODLIC	LAND	SURVEI		レアクロンド

tondose Nio	C-5
Index No.	

State of Wisconsin ss.						
County of Forest						
I William B. Cochrane do hereby certify that on the 7th day of May 19.85, I found evidence of the West Quarter corner of Section 5 Township 40 North, Range 14 East Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.						
Resident witnesses:						
David Brownell						
TonyTillman						
;						
SECTION 5						

O = Corner monument restored.

History of original corner establishment:

Original Government Survey in 1865 by William E. Daugherty. North between Sections 5 and 6, 40.00 chains, set Quarter Section Post to Sections 5 and 6, from Which the following bear;

S33°E 118 1ks. Aspen 3" N11°W 234 1ks. Aspen

Description of corner evidence found:

No corner evidence was recovered.

The corner position was re-established at proportionate distance and on ling between the Northwest and Southwest Section Corners of Section 5.

Description of monument and accessories I established to perpetuate the original location of this corner. At the re-established corner position set a $2\frac{1}{2}$ " diameter aluminum pipe monument, 5 feet long, 4 feet in the ground, with an aluminum cap stamped; T40N R14E, 1/4, S5, S6, 1985, S-1107. From which the following new blazed and scribed bearing trees bear;

12.26 feet N60°E Cedar S44°E 30.03 feet Cedar 1.00 feet Steel Sign Post SW

Dated at	Hiles	, Wis., this	8th	day of	January	, 19,86
Signature.	County Surveyor, Regist	Acceptant Surveyor	Land S	urveyor	Reg	istration No. S-110
Office of Regi		-		•		certify that the within
nstrument w	ister of Deeds, County of as filed in this office for r	ecord on the	11t	h day c	of March	19.87
$1t 3:30_{0}$	$\operatorname{clock} P_{-} M_{-}$					
	Paul Asch	nbrance	1			
•	(Register of De	eds)				


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

1

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



(i) 1. William B. Cochrane
(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Villiam B. Cochrane October 14, 198

Certificate ready for filing:

District Ranger

Date