U.S.	PUBLIC	LAND	SURVEY	MONUMENT	RECORD
------	--------	------	--------	----------	--------

		N _	9
Index	No	1 W	

State of Wisconsin County of Forest Gary L. Pisoni certify that on the 24th day June 19 86, I found evidence of the Northwest	History of original corner establishment: Original Government Survey in 1865 by Wm. E. Daugherty. Dependent resurvey of 1950 found the remains of the original bearing trees and a 4" squared cedar post. On 6/9/70, Jean Resvick, a land surveyor with the U.S. Forest Service replaced the cedar post point with a 2½" diameter by 5' long galvanized iron pipe with a brass cap stamped: T40N, R14E, S16, S17, S20, S21, 1970, S-802 from which the following bear:				
Foundation Section 21 Foundation 40 North, Range 14E Fourth Principal Meridian, as described hereon; and that from this evidence is described a new monument and accessories as described hereon to perpetuate the original ocation of this corner. Resident witnesses:	Maple 12", S.41°54'W. 42.77 feet Balsam 5" N.32°16'W. 16.05 feet Northwest corner of cabin S.81°17'E. 52.55 feet Description of corner evidence found: Monument as described and inpplace, from which the following bear: Maple 15" S.41°54'W. 42.77 feet Balsam 8" N.32°16'W. 16.05 feet Northwest corner of cabin S.81°17'E. 52.55 feet				
Kyle Erickson	Description of monument and accessories I established to perpetuate the original location of this corner. Blazed and scribed the following new bearing tree: Balsam 8" S.34°E'. 9.46 feet				
SECTION 21	Dated at Iron River, MI, Wisk this 2nd day of November 19.87. Signature Land Surveyor Registration No. S-1634 (County Surveyor, Registered Land Surveyor, or other duly authorized official)				
Corner monument restored.	Office of Register of Deeds, County of Forest , I hereby certify that the within instrument was filed in this office for record on the 18th day of March , 1988 at 12-50 o'clock P				


Describe any material discrepancy between the location of the corner as restored or (e) reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See Drawing Below.

(r) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(96h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used, as evidence or used for proportioning in determining the corner location?



Date