NUMB	Ç
DOCUMENT	A A DE

ER.

			U.S.
State	of Wisc	onsin	} ss.
County of	Forest	, ,	} SS.
I Gary	L. Pisoni	L	do hereby
certify that	on the	6th	day
			89., I found
Township	40	, N	North, Range
		-	al Meridian,
	_		this evidence daccessories
		•	the original
location of t			-
Resident wi	tnecce:	-	
Kesident wi	messes.		
		·	***************************************
	•		

		•••••	
 .			
	· ·	1 .	
		I	1
	•	 	[
	·	'	i
] 1	
	SECTI	ON 32	
	36011	014 32	¦
ĺ	•	,	!
			.
 		 :	<u> </u>
		·	
) 	. !) 	
2+ I	.!		
		ı	· '

= Corner monument restored.

History of original corner establishment:

Original Government Survey in 1865 by William E. Daugherty. North between Sections 31 and 32, 40.00 chains, set Quarter Section post to Sections 31 and 32, from which the following bear;

Birch	8"	S.30°E.	10 links
Birch	^ 10"	s.87°E.	20 links

Description of corner evidence found:

No corner evidence was recovered.

The corner position is restored at proportionate distance and on line between the Northwest and Southwest Section corners of Section 32.

Description of monument and accessories I established to perpetuate the original location of this corner.

At the corner position, set a $2\frac{1}{2}$ inch diameter aluminum pipe monument, 3 feet long, 33 inches in the ground, with an aluminum cap stamped; T40N, R14E, 1/4, S31, S32, 1989, S-1634. From which the following new blazed and scribed bearing trees bear (all measurements are taken to a nail in side of tree):

Sugar Maple	9''	N.08 E.	33.94 feet
Sugar Maple	10"	S.50°E.	9.98 feet
Sugar Maple	10"	s.04°W.	9.85 feet
Sugar Maple	11"	N.61°W	5.58 feet
Steel sign post		s.60°w.	0.88 feet

Dated at Iron River, MI	, Wis., this	Znd	day of	November	19.89
Signature Huy I. Leson	Title	Land Sur	veyor	Registration	n No ^{S-1634}
(County Surveyor, Registered Land Surveyor, or other duly authorized official)					
Office of Register of Deeds, County of	So	LST	····		that the within
Signature Land Surveyor Registration No.S-1634 (County Surveyor, Registered Land Surveyor, or other duly authorized official) Office of Register of Deeds, County of Local Land Surveyor, or other duly authorized official) I hereby certify that the within instrument was filed in this office for record on the Land Surveyor (lay of Local Land Surveyor), 19.90 at 10:45 o'clock A. M.					

	(Register of Deeds)	
	11/-1/	
By (Slan)	Millo	Deputy


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through lost corner proportionate methods.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



Gary L. Pisoni

(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature January J. France January 2 1990 Signature

Survey requested by;

District Ranger

9-18-90

Date