32

NUMBER

_	Fores	<u> </u>	J
certify that of Junevidence of corner of	on thethe	22nd , 19 South Qua	85, I for
Township 14 East as described I establishe as described location of t	40 hereon; and a new many to hereon to	ourth Prince out that from to nument a perpetuar	North, Racipal Meriding this evide accesso
Resident wi		•••••••••••••••••••••••••••••••••••••••	
State Pla N- 268,	591.4400		:
E-2,324,	10461,550		
E-2,324,		-	

State of Wisconsin

SS.

O = Corner monument restored.

History of original corner establishment:

Original Government Survey in 1858 by Artemas Curtis. Dependent Resurvey in 1945 by Hugh Crawford. From the remains of original bearing trees, set a concrete monument, 24 ins. long, 6 ins. diam., 18 ins. in the ground, with a brass cap mkd; T40N, R14E, 1/4, S3, S34, T39N, 1945. From which the following bear; N 5°15'W $71\frac{1}{2}$ 1ks. Hemlock

99 1ks.

Description of corner evidence found:

Maple

Found monument as described and in place, from which the following bear;

S37°30'W

N 5°15'W 47.19 feet Hemlock S37°30'E 65.34 feet Map1e Alongside Monument Steel Sign Post North

Description of monument and accessories I established to perpetuate the original location of this corner.

None

Dated at Hiles , Wis., this 7th day of March , 19 86 Signature William B. Cochrane Title Land Surveyor Registration No. S-1107 (County Surveyor, Registered Land Surveyor, or other duly authorized official) Office of Register of Deeds, County of Forest , I hereby certify that the within instrument was filed in this office for record on the 11th day of March 1987 at 3:30 o'clock P. M. (e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (i) the gerner as restored or reestablished, and (2) to at least 2 of the witness menuments shown on the drawing in (d), above.

See drawing below.


ì.

100

(f) Was the corner restored through acceptance of (j) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, impluding the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



12" Maple S37°E, 65.34 feet

WILLIAM B.

COCHRANE

S-1107

HILES,

WISCONSIN

(i) 1. William B. Cochrane
i(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

William B. Cochrane October 7, 1986 Signature

Survey requested by; Agrant 3-9-

District Ranger ' Date

12221
NUMBER
OCUMENT

State of Wisconsin } ss.							
County of Forest							
I. William B. Cochrane, do hereby certify that on the 22nd day of July, 19.85, I found evidence of the North Quarter corner of Section 3 Township 39, North, Range 14. East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.							
Resident witnesses:							
Tony Tillman							

State Plane Co-ordinates N- 268,591.4400 E-2,324,164.1990							
SECTION 3							

O = Corner monument restored.

History of original corner establishment:

Original Government Survey in 1858 by Artemas Curtis. Dependent Resurvey in 1945 by Hugh Crawford. From the remains of original bearing trees, set a concrete monument, 24 ins. long, 6 ins. diam., 18 ins. in the ground, with a brass cap mkd; T40N, R14E, 1/4, S34, S3, T39N, 1945. From which the following bear;

и 5°15'W $71\frac{1}{2}$ 1ks. Hemlock S37°30'E 99 1ks. Maple

Description of corner evidence found:

Found monument as described and in place, from which the following bear;

N 5°15'W 47.19 feet Hemlock S37°30'E 65.34 feet Maple Steel Sign Post Alongside Monument North

Description of monument and accessories I established to perpetuate the original location of this corner.

None

Dated at	Hiles	, Wis., this.	7th	day of ¹	March	, 19 ⁸⁶
	Man B. Co		Land S	urveyor	Reg	istration No. S-1107
instrument was at 3:30 o'cl	s filed in this office ock P. M	for record on the	Forest 11th	day o	, I hereby f March	certify that the within 19 87
Ву			Depu	ty		


Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness manuments shown on the drawing in (d), above.

See drawing below.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



12" Maple S37°E, 65.34 feet

(i) i. William B. Cochrane
(type or print name) certify that the corner location shows on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

October 7 1986

Survey requested by;

Signature

* 4

District Ranger

Date

COCHRANE

S-1107

HILES,

WISCONSIN