## U.S. PUI

	LAND SUR					Index No. Z-25
	ory of original corner				_	
_		_	_		is. Dependent Resurv	-
		-			ring tree, set a cor with a brass cap mka	
		_			following bear;	1, 140N, KIAD,
	Poplar	5"	N30°30'E	58 1	0	
	Maple	12"	S80°00°E	215 <sup>1</sup> <sub>2</sub> 11	ks.	
	W. Pine		S55°15'W	84½11	ks.	
	Spruce	8''	N82°45'W	90 11	ks.	
Desc	ription of corner evid	dence found:				
Foun	d monument as d	escribed an	nd in place, i	rom whi	chithe following bea	ar;
-	Poplar	14"	N30°30"E	38.28	feet	
	Maple	2211	S80°00'E	141.90	feet	
	W. Pine(Stump)		S55°15'W	55.44	feet	_
	Spruce(Stump)		N82°45'W	59.40	feet	
•	Steel Sign Pos	t	South	0.50	feet	•
						•
Desc	ription of monument	and accessori	ies I established t	o perpetua	te the original location of	this corner.
	ed and scribed	•				-
	Spruce	15"	S59°W	67.45	feet	
•	Spruce	811	N71°W	50.70	feet	<del>-</del>

N- 268,883.4340	brazed and scribed	the id	errowing new	bearing trees
E-2,337,278.9490	Spruce	15"	S59°W	67.45
	Spruce	8"	N71°W	50.70

O = Corner monument restored.

State of Wisconsin

County of Forest

I William B. Cochrane , do hereby

certify that on the 22nd day of August 19.85, I found evidence of the Southeast Section

Corner of Section 36
Township 40 North, Range

14 East Fourth Principal Meridian,

as described hereon; and that from this evidence

as described hereon to perpetuate the original

Tony Tillman

State Plane Co-ordinates

location of this corner.

Resident witnesses:

established a new monument and accessories

Dated at	Hiles	, Wis., this	27th	dav of	February		1986
		chraue Title		-		_	
J	(County Surveyor	, Registered Land Surve	yor, or other duly	authorized offi	cial)		
Office of Reg	ister of Deeds, Cou	nty of Fores	st		, I hereby c	ertify that th	e with
	C1-1 '1 ' rc	. 1 .1	I I + h		Mamak		4 a D =

instrument was filed in this office for record on the <u>lith</u> day of <u>March</u> at 3:30 o'clock P. M.

(Register of Deeds)


(e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(f) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(9&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



(i) I, William B. Cochrane
(type or print name; certify that the corner location shows on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

William B. Cockrane October 7, 1986
Signature

Survey requested by; Award Control 3-9-

District Ranger

Date

WISCONSIN

32316

## U.S. PUBLIC LAND SURVEY MONUMENT RECORD

History of original corner establishment:

Poplar

Index	No. A-25
-------	----------

State of Wisconsin
County of Forest
I William B. Cochrane , do hereby certify that on the 22nd day of August , 19 85 , I found evidence of the Northeast Section corner of Section 1  Township 39 , North, Range 14 East , Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.
Resident witnesses:
Tony Tillman
***************************************
State Plane Co-ordinates N- 268,883.4340 E-2,337,278.9490
SECTION 1
O = Corner monument restored.

M	aple	12"	S80°00'E	215½ 1ks	s.		
; W	. Pine	16"	S55°15'W	84½ 1ks	<b>3.</b>		
. S	pruce	8"	N82°45'W	90 1ks	S.		
Descrip	otion of corner ev	vidence found	:				
Found :	monument as	described	and in place,	from which	ch the fol	llowing bear;	
	~~~	14"	N30°30'E	38.28	foot		
	spen	22"	S80°00'E	141.90			×
	aple Pino(Stump		S55°15'W	55.44			×
	. Pine(Stump pruce(Stump)		N82°45'W	59.40			X
	teel Sign Po		South		feet		<i>\( \)</i>
ى	reer sign ro	SL	Bouth	0.50	TEEL		
				•			9
Descrip	otion of monume	nt and access	ories I established	to perpetua	ite the origin	nal location of this cor	ner.
Blazed	and scribed	the follo	wing new bear	ing trees	:		<del>-</del>
220200					•		γ ~
S	pruce	15"	s59°W	67.45	feet		~
S	pruce	811	N71°W	50.70	feet		
*	•						
	٠.	,					
D 1	. Hiles		3377	27th	1 6	February	10 86
	_	_			-		
Signatu	reWilliam K	3. Cochro	Title	Land S	Surveyor	Registratio	on No. S-1107
•	(County	y Surveyor, Reg	istered Land Surveyo	or, or other duly	y authorized of	fficial)	
Office o	of Register of De	eds, County	of Fores	t		I hereby certify March	y that the withi
instrum	ent was filed in	this office for	record on the	lith	day o	<sub>of</sub> March	19.07
at3::	.30 <u>o'clock</u>						
	AD 1	Souls -	renner				
	Jaux	(Register of D			-		
		(Ivegiates of L	, ccus,				
Ву				Deputy	,		
•							

Original Government Survey in 1858 by Artemas Curtis. Dependent Resurvey in 1945

S1, S6, S31, S36, T39N, 1945. From which the following bear;

N30°30'E

by Hugh Crawford. From the remains of an original bearing tree, set a concrete monument

3 feet long, 5 ins. diam., 28 ins. in the ground, with a brass cap mkd; T40N, R14E, R15E,

58 1ks.


Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

(f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

(g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?



(i) i, <u>William B. Cochrane</u>
(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Signature Date Date

Survey requested by: Leval Sept 8-9-8/

District Ranger Date

WILLIAM B.

COCHRANE

S-1107

HILES,

WISCONSIN