

Stock No. 26273
DOCUMENT NUMBER
145389


U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Index No. V-7

State of Wisconsin }
County of Forest } ss.

I, William B. Cochrane, do hereby
certify that on the 4th day
of December, 1990, I found
evidence of the South Quarter
corner of Section 29
Township 41 North, Range
13 East, Fourth Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.

Resident witnesses:



● = Corner monument restored.

History of original corner establishment:

Dependent Resurvey in 1942 by Guy R. Veal and Hugh B. Crawford. N88°22'W
between Sections 29 and 32, at proportionate distance of 39.41 chains, set
a concrete monument, 2 feet long, 4 inches in diameter, with an iron post
and brass cap in center marked; 1/4, S29, S32, 1942. From which the following
bear;

Maple	8"	N45°E	37 links
Maple	10"	S16°E	12 links

Description of corner evidence found:

Found the monument as described and in place, from which the following bear;

Maple	16"	N45°E	24.38 feet	Blazes healed over.
-------	-----	-------	------------	---------------------

No other corner evidence was recovered.

Description of monument and accessories I established to perpetuate the original location of this corner.

Blazed and scribed the following new bearing tree;

Maple	7"	N13°W	29.05 feet
-------	----	-------	------------

Set Steel Sign Post	South	1.00 feet
---------------------	-------	-----------

Dated at Hiles, Wis., this 14th day of February, 1991

Signature: William B. Cochrane Title: Land Surveyor Registration No. S-1107
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Forest, I hereby certify that the within
instrument was filed in this office for record on the 31st day of August, 1992
at 10:15 o'clock A.M.

Paul Aschenbrenner
(Register of Deeds)

By Deputy

44113290020

- (e) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.

See drawing below.

- (f) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through acceptance of a found perpetuated location.

- (g&h) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

7" Maple, (New bearing tree)
N13°W, 29.05 feet

16" Maple
N45°E, 24.38 feet

Quarter Corner $\frac{S29}{S32}$

Steel Sign Post
South, 1.00 feet

Affix Land Surveyor Seal



- (i) I, William B. Cochrane
(type or print name) certify that the corner location shown on this record was determined by me or under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

William B. Cochrane
Signature

1/21/92
Date

Survey requested by;

Pamela Yachin
District Ranger

1/22/92
Date