FORM NO. 985-A

U.S. P	UBLIC	LAND	SURVEY	MONUMENT	RECORD
--------	-------	------	--------	----------	--------

		P-	17
Index	No		l 8

State of Wisconsin
County of Forest
I Gary L. Pisoni , do hereby certify that on the 16th day of July , 19.91 , I found evidence of the Quarter Corner
Resident witnesses:
);
***************************************
SECTION 23
1 1 1
<del>-</del>
1 1 1
1 1 1

= Corner monument restored.

History of original corner establishment:
Original Government Survey in 1865 by William E. Daugherty. North 40.00 chs. set
Quarter Section Post to Sections 22 and 23.
In 1962, Jean Resvick, a Land Surveyor with the Forest Service found a 3"
square wood post 3 feet above the ground. He was not able to tie this post
in with any bearing tree evidence.

Original Bearing Trees.

Sugar 14" N89°W 42 İks.
Birch 14" S88°E 17 lks.

Description of corner evidence found:

No corner evidence was recovered. The post described above was not recovered nor any original corner evidence.

I restored the corner position at proportionate distance and on line between the Southwest Section Corner of Section 23 and the Meander Corner between Sections 22 and 23.

Description of monument and accessories I established to perpetuate the original location of this corner. At the corner position, set a  $2\frac{1}{2}$  inch diameter aluminum pipe monument, 3 feet long, 3 inches above the ground, with an aluminum cap stamped; T41N R14E, 1/4, S22, S23, 1991, S-1634. From which the following new blazed and scribed bearing trees bear; (measurements taken to a nail in side of tree)

S. Maple	811	N57°E	21.17 feet
S. Maple	811	S50 <sup>O</sup> E	31.71 feet
S. Maple	8"	s37 <sup>o</sup> W	39.29 feet
S. Maple	7"	N59 <sup>O</sup> W	14.32 feet
Steel Sign Post	•	North	0.76 feet

Dated at	lron River,	MI XXX	this	16th	day of	February	1992
Signature A	lay I Pas	one	Title	Land	Surveyor	Rcgista	ration No. S-1634 rtify that the within
0.5	(County Surve	yor, Registered La	nd Survey	or, or othe	r duly authorized	f official)	
Office of Regist	er of Deeds, C	County of	ocest		f	I hereby ce	rtify that the within
instrument was	filed in this o	ffice for record of	on the		da	y of Males	19./
at 10:45 .o'cle	ock /	. M 🅢					
	Paul -	HSChen	bren	سعہ	8		
	(Reg	ister of Deeds)					

Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (d), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 2 of the witness monuments shown on the drawing in (d), above.


See drawing below.

(r) was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Restored through lost corner proportionate metheds.

(9kh) was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning in determining the corner location?

Reestablished through lost corner proportionate methods.



arr

Date

District Ranger

Survey requested by;